FLEET TEAM DIGEST

737MAX-FTD-34-22006

Issue Title : Flight Management Computer (FMC) Operational Software (OPS): In-service FMC Resets & FMC Disagree messages

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
08/11/2022	03/27/2026	01/16/2026
Estimated Completion Date	**Next Update Date**	
01/31/2028	09/30/2026	

Revision Description

Updated the following section(s):

- Milestones

Description

The purpose of this article is to provide information related to FMC resets and disagree messages, with regard to the specific Flight Management Computer (FMC) Operational Software (OPS) Update (U12, U13, U14) installed on 737 MAX aircraft.

This FTD is strictly related to known Operational Software caused resets (not Hardware).

For information on Hardware resets, review referenced FTD articles on FMC Hardware model C1 SRAM.

- *FMC OPS U14.1/14.2 will be subject to the AFM Limitation for RNP < 0.3nm when used with C1 FMC Hardware*

Status

Boeing and GE Aviation have received numerous reports of 737 MAX operators experiencing FMC resets and disagree messages, utilizing various FMC OPS updates. The following FMC reset and FMC disagree issues are itemized by operational software update version:

U12
- FMC Reset due to data link function retrieving abeam waypoint information for an alternate plan abeam waypoint (Fixed in U13)

U13
- FMC DISAGREE messages are considered nuisance for the following cases (Fixed in U14):

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- Due to a miscompare of the two FMC's internal lateral packet data provided to the FMC Guidance function when on-ground.
- Due to a miscompare of the FMC's Roll Command when on-ground.
- Due to disagreement between the FMC and ECS packs related to a temperature miscopare due to an erroneous FMC calculation close to, or after flight complete (737 MAX only).
- Due to a miscompare of the two FMC's internal lateral packet data provided to the FMC Guidance function when in-air. The condition occurs in-air when guidance enters into a Missed Approach HOLD, where the inbound course is close to the reciprocal of the hold inbound course.

- Secondary FMC resets due to partial crossload of undefined primary route (Fixed in U14)

- Erroneous ARINC Channel Wrap Failures (Fixed in U14)

- In-Service PAST_NUMBER_OF_SEGMENTS exception (error code 0x93) (Fixed in U14)

- Glitch Timer Circuitry test software improvement (Fixed in U14)

U14
- FMC Reset due to VECTOR & Discontinuity (DISCO) Combination (Fixed in U14.1) - OMB released | ***See Milestones section.***

- FMC Reset on Approach when entering airway/airway in inactive route (Fixed in U14.1)

- FMC Reset due to CPDLC function with FANS enabled (Proposed fix in U14.2) - OMB released

Interim Action

To determine if a FMC Reset did occur, Boeing asks operators to review the referenced FTD articles on In Service Faults for further instruction on what action items are recommended to flight & maintenance crews.

Final Action

Incoporate the service bulletins discussed in the milestones.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

737 MAX - FMC OPS U14.1 - Boeing Service Bulletin Release | 28-May-2022 (Complete)

737 MAX - FMC OPS U14/U14.1 - CPDLC function with FANS enabled OMB Release | 12-Sep-2022 (Complete)

737 MAX - FMC OPS U14 - VECTOR/DISCO Combination OMB Release | 13-Oct-2023 (Complete)

FMC OPS U14.2 - 737 MAX - Certification | No earlier than 2028 (Target)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

FMC OPS U14.2 - 737 MAX - Production Incorporation | No earlier than 2028 (Target)

FMC OPS U14.2 - 737 MAX - Service Bulletin Release | No earlier than 2028 (Target)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-34-19004		
Fleet Team Digest Article (FTD)	737MAX-FTD-34-18008		

Related Categories

- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991