FLEET TEAM DIGEST

737MAX-FTD-34-23003

Issue Title : Honeywell ATC Transponder DC Power Supply Improvements

Airplane Model	ATA	Minor Model(s)
737MAX	3453-02	-8, -8200, -9

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
10/12/2023	10/12/2023	08/08/2023

Estimated Completion Date	Next Update Date

Applicability

737NG and 737MAX airplanes utilizing Honeywell ATC Transponder, PN: 066-01212-0301 without MOD 8.

Description

This FTD provides information regarding modifications being made available to improve reliability of the DC Power Supply within Honeywell ATC transponder, PN: 066-01212-0301.

Background

Boeing and Honeywell have received multiple reports of Honeywell ATC transponder, PN: 066-01212-0301 experiencing fault code 14. These events have been found to be related to the TR44 MOSFET installed in the DC Power supply of the unit, and is used in the circuitry designed to provide the energy needed for the transmit pulse during normal operation.

Status

Boeing has been coordinating with Honeywell in order to improve the reliability of this ATC transponder unit and after reviewing the thermal dissipation requirements of the TR44 MOSFET junctions, it has been found that an increase in the derating of this part would increase reliability of the unit. A replacement MOSFET has been identified which has a higher temperature rating to better handle the power dissipation from this circuit. Required testing has been completed and a Honeywell Component Service Bulletin has been released to allow installation of the new MOSFET part.

Interim Action

Operators should monitor the reliability of Honeywell ATC transponder, PN: 066-01212-0301, in their fleet to determine if

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

incorporation of the Honeywell Component Service Bulletin would be beneficial to improve reliability of this unit for their fleet.

Final Action

Boeing has developed this FTD to notify operators of the availability of Honeywell Component Service Bulletin TRA-100B-34-08 (D202301003430), which improves reliability of Honeywell ATC transponder, PN: 066-01212-0301, by installing a new TR44 MOSFET component.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: NOV-2021 (Complete)
Solution Selected: DEC-2021 (Complete)
Production Incorporation: JUL-2023 (Complete)
Honeywell Component SB Available: 29-AUG-2023 (Complete)

Operator Action

Operators should be aware that a Honeywell Component Service Bulletin (CSB) has been released which can improve reliability of the Honeywell ATC transponder, PN: 066-01212-0301. Please contact Honeywell for further details or incorporation of this CSB.

Supplier Information

HONEYWELL INTERNATIONAL INC.

15001 NE 36TH ST REDMOND, WA 98052-5317

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Other	Honeywell Component SB: TRA-100B-34-08	0	08/29/2023

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
ATC Transponder	066-01212-0301	Honeywell International Inc.	066-01212-0301

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- CRC - Component Reliability Collaboration : Collaborative process to eliminate component removals in production and the during the first year of new airplane in service

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991