FLEET TEAM DIGEST

737MAX-FTD-34-24002

Issue Title : 737MAX with FMC U13 software, Unintended Loading of Duplicate Fix

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-10, -7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
02/28/2024	09/09/2026	11/14/2024
Estimated Completion Date	**Next Update Date**	

Revision Description

No Updates required - FMC U14 Software released in 2020. This FTD is now closed.

Description

There is a known issue with U12/U13 OPS in which the FMC incorrectly loads an unintended waypoint into the active route via uplink uM74 Direct To [position] or uM79 Cleared To [position] via [route clearance]; the only waypoints prone to this issue are duplicate waypoints in the FMC Navigation Database (NDB). This issue is applicable to operators that use CPDLC features to load flight plans and route changes. The condition is the result of the FMC failing to collapse an uplinked position waypoint that is a duplicate in the NDB, to an existing waypoint in the active route. Instead, the FMC selects the duplicate closest to the preceding flight plan fix, if one exists, else the origin airport. When this occurs, a route discontinuity will be introduced between the loaded fix and the active fix. Refer to the appendix for example figures identifying the flight deck effects.

Status

The issue was originally discussed in 737NG-FTD-34-16004 “U12 In-Service Issues”. A fix has been incorporated into the FMC U14 software upgrade refer to 737-SL-34-251 “Flight Management Computer - Update 14”. This issue was also covered in 737NG-FTD-34-16004 and 737MAX-FTD-18005 for the “FMCS- Update 14.0”.

The following FMC U14 Service Bulletins have been released:
SB 737-34-3065 (737MAX)
SB 737-34-3066 (737NG)

Interim Action

Operators utilizing U12/U13 software should be aware of the potential for the loading of an incorrect fix when attempting to load route changes via CPDLC uplinks uM74 Direct To [position] or uM79 Cleared To [position] via [route clearance]. Flight crews that identify that an incorrect fix has been loaded should erase the route modification prior to attempting further route changes. The uplinked clearance should be rejected and ATC should be contacted via voice to clarify the route change.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

Installation of FMC U14 software, refer to SB 737-34-3065 (737MAX) and 737-34-3066 (737NG).

Milestones

Service Bulletin Available: 737-34-3065 December 2020 (737MAX)

Service Bulletin Available: 737-34-3066 January 2020 (737NG).

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737NG-FTD-34-16004		
Service Letter (SL)	737-SL-34-251		
Fleet Team Digest Article (FTD)	737MAX-FTD-34-18005		
Service Bulletin (SB)	737-34-3065		
Service Bulletin (SB)	737-34-3066		
Fleet Team Digest Article (FTD)	737NG-FTD-34-16010		

Related Categories

- Flight Operations : Flight Operations

Attachments:

a) Appendix - Example

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991