FLEET TEAM DIGEST

737MAX-FTD-34-24003

Issue Title : GLU-2100 Multi-mode Receiver Using Correction Values Past the Timeout Period

Airplane Model	ATA	Minor Model(s)
737MAX	3458-00	-10, -7, -8, -8200, -9

Other Model(s)	ECCN
747, 737NG, 777, 767	9E991

Originated Date	Last Revised Date	Created On
10/08/2024	09/22/2026	09/15/2026

Estimated Completion Date	Next Update Date
01/31/2027	11/18/2026

Revision Description

No update.

Applicability

All 737MAX airplanes with Multi-Mode Receiver (MMR) GLU-2100 P/N 822-2532-100 installed.

Description

Collins Aerospace has identified a non-compliance impacting software on the 3G Multi-Mode Receiver (MMR), model GLU-2100, P/N 822-2532-100. Minimum Operational Performance Standards (MOPS) require the MMR to discard timed out messages within a specific time period. However, Collins Aerospace discovered that under certain conditions, the GLU-2100 MMR, P/N 822-2532-100, uses the Satellite Based Augmentation System (SBAS) correction values beyond the timeout period specified by the MOPS.

When this occurs the MMRs may be unable to notify the flight crew when the integrity of the SBAS qualified GNSS position may be compromised. This could cause the Actual Navigation Performance (ANP) to show better accuracy than it actually is. This does not effect the accuracy of the GPS position. Though some Lateral Navigation (LNAV) approaches have the potential to be impacted (specifically ANP approaches). All precision approaches are unaffected.

Status

Boeing has evaluated this non-compliance for near term safety and has determined that this condition does not affect the safe operation of the airplane at this time.

Collins Aerospace is currently working to release a software fix to resolve this condition on the GLU-2100 MMR.

This condition was found after a ground system update to the European Geostationary Navigation Overlay System (EGNOS) system was applied in November of 2023, which includes more extensive use of a parameter value in the Message Type 6 (MT6)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

message to improve the integrity of the service. Although this condition is currently known to affect EGNOS users, SBAS providers in other regions that utilize this parameter in a similar fashion may also be affected.

Interim Action

Based on the current safety evaluation, there is no immediate action needed by customers. Boeing will continue to deliver airplanes with the non-compliant software until the new Collins GLU-2100 MMR software containing this fix is certified for production installation.

Final Action

The new Collins GLU-2100 MMR software will be certified and incorporated into Boeing production to alleviate the non-compliance.

A Service Bulletin will be released to update the GLU-2100 MMR software for retrofit on in-service airplanes.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Production Incorporation: DEC 2026 (Estimated)
Service Bulletin Available: JAN 2027 (Estimated)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Other	EASA Safety Information Bulletin No. 2024-03	R1	02/07/2024

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
GLU-2100 MMR	822-2532-100	Collins	

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991