FLEET TEAM DIGEST

737MAX-FTD-34-24007

Issue Title : 737MAX Unable to LOGON due to incorrect Admin Region Selector (ARS) configuration when using Rockwell Collins CMU-900 while in Eurocontrol region.

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-10, -7, -8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
09/18/2026	09/18/2026	09/25/2024
Estimated Completion Date	**Next Update Date**	

Applicability

Applies to all 737 MAX airplanes.

Description

737NG and 737MAX airplanes with FANS-2 or with Aeronautical Telecommunication Network Baseline 1 (ATN B1) enabled in the Rockwell Collins (RC) Communications Management Unit CMU-900 have reported events where they are unable to LOGON to ATN Navigation Service Provider (NSAP) while flying over European airspace when using the incorrect Administrative Region Selector (ARS) configuration in the RC CMU-900.

Background

Eurocontrol has reported to Boeing that numerous operators have misconfigured their aircraft avionics resulting in ATN NSAP addresses with the incorrect Administrative Region Selector (ARS) fields. Per ICAO Eur Doc 028 NSAP Address Registry, the ARS field should be set to the unique 24-bit ICAO Aircraft Address. Misconfiguration of this field can result in the CPDLC ground system rejecting logons sent from the aircraft. On the Rockwell Collins CMU-900, the ARS field is manually programmed into the CMU's Airplane Personality Module (APM) via AMM task 23-27-35-700-802.

Status

Boeing has identified limitations in the description contained in Section 23-27-35 (ACARS System, Airplane Personality Module) of some operator's Aircraft Maintenance Manual. Specifically, Task 23-27-35-700-801 (ACARS APM Data Verification Check) and Task 23-27-35-700-802 (ACARS APM Software Installation) do not contain the full APM programming instructions (pages 1-5) and instead may only contain instructions for pages 1-3.

Interim Action

Operators should confirm that the 24-bit ICAO Aircraft Address in LSK 1L on the ACARS-IDENT BLK PGM page 2/5 matches the ARS value in LSK-2L on the ACARS-IDENT BLK PGM page 5/5. The ACARS-IDENT BLK PGM pages are accessed from the APM

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

MENU which is accessed via the password-protected ACARS-PROTECTED MENU. See IDENT BLK PG example.

1-Refer to AMM Task 23-27-35-700-801 for page access instructions to the ACARS-IDENT BLK PGM pages.

2-Select NEXT on the IDENT BLK PGM page until page 2/5 is shown

3-Refer to value shown from page 3/5 for ICAO ADDR: 123456 (6 digit Hexadecimal) to be same as ARS value.

4-Select NEXT on the IDENT BLK PGM page until page 5/5 is shown

5- Make sure that the value for ARS: 123456 (6 digit Hexadecimal) matches ICAO ADDR from page 2/5.

Final Action

Boeing has updated Aircraft Maintenance Manual. Specifically, Task 23-27-35-700-801 (ACARS APM Data Verification Check) and Task 23-27-35-700-802 (ACARS APM Software Installation).

Milestones

AMM Instructions Update:

737MAX: Included Coverage for ACARS-IDENT BLK PGM pages 4 and 5 under airplanes with Rockwell Collins Core Software 815-5679-505 (AMM has been updated)

737NG: Included Coverage for ACARS-IDENT BLK PGM pages 4 and 5 for airplanes with ATN Core Software and covered by POST SB 737-23-1390 (AMM has been updated)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737NG-FTD-23-23001		

Related Categories

- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991