FLEET TEAM DIGEST

737MAX-FTD-34-25004

Issue Title : Honeywell IMMR Global GPS Outage

Airplane Model	ATA	Minor Model(s)
737MAX	3458-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
12/05/2025	09/22/2026	05/11/2026

Estimated Completion Date	Next Update Date

Revision Description

Revised Status, Final Action, and Milestones.

Applicability

Airplanes with Honeywell Integrated Multi-mode Receivers (IMMR) Part Number 69002600-0101 installed.

Description

From May 21, 2025 00:00 UTC to May 22, 2025 17:00 UTC operators with Honeywell IMMRs installed in their fleet reported dual GPS loss events.

Analysis indicated that the Global Positioning System (GPS) software was experiencing periodic resets. While on the ground, symptoms could persist for up to two hours. In some cases, cycling the GPS power, or repositioning the aircraft recovered the GPS units. In flight, the periodic GPS software resets would occur for a few minutes before resuming normal operation on its own.

An investigation connected the IMMR GPS loss with a change in output from the United States Space Force (USSF) GPS Satellite pseudo-random noise (PRN) code 37. The GPS satellite PRN 37 started transmitting as part of a test program as noted in NANU#2025017. This test programming included “default NAV data”. Signals from PRN 37 are intentionally received within the IMMR for integrity monitoring purposes. The change in the GPS satellite created an exception in the IMMR software architecture, causing a reset.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

On May 22, 2025, at approximately 17:00 UTC, the satellite broadcast was changed back to non-standard code to prevent IMMR receivers from tracking the satellite. This change has resolved the IMMR losing GPS functionality when receiving data from PRN 37.

Status

Honeywell released an IMMR STC fix (software update) on 9/19/25 to prevent future outages due to GPS satellite data format changes.

Boeing has certified the new IMMR software.

Interim Action

None

Final Action

Boeing incorporated the new software into production starting at L/N 9749. Boeing notes that this is applicable only to production aircraft with the IMMR option selected.

Boeing released Service Bulletin 737-34-4410 to retrofit the existing 737MAX fleet.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 22-MAY-2025 (Complete)

Honeywell STC Available: 19-SEP-2025 (Complete)
Production Incorporation: 12-JUNE-2026 (Complete)
Service Bulletin Available: 08-JUNE-2026 (Complete)

Supplier Information

HONEYWELL INTERNATIONAL INC.

15001 NE 36TH ST

REDMOND, WA 98052-5317

Telephone: 800-601-3099 (Toll Free U.S.A./Canada)

Telephone: 602-365-3099 (International Direct)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Multi-Operator Message (MOM)	MOM-MOM-25-0208	1	05/23/2025
Other	Honeywell Article 000046154		06/02/2025
Service Bulletin (SB)	737-34-4410		
Airplane Configuration Bulletin (ACB)	2026-ACB-0001		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Integrated Multi-Mode Receiver	69002600-0101	Honeywell International, Inc.	

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991