FLEET TEAM DIGEST

737MAX-FTD-34-25005

Issue Title : Flight Management Computer (FMC) Actual Navigation Performance (ANP) Increasing in FMC OPS U14.1

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-10, -7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	7E994	

Originated Date	Last Revised Date	Created On
03/27/2026	08/28/2026	06/29/2026
Estimated Completion Date	**Next Update Date**	
12/31/2026	12/31/2026	

Revision Description

No updates

Applicability

Applicable to all 737 MAX models.

Description

Boeing has received reports from an operator using FMC OPS U14.1, where the Actual Navigation Performance (ANP) has reached 3 Nautical Miles (NM) and increasing just before entering oceanic airspace. This may be caused when one of the FMCs detects an out-of-bounds step position change in the onside Global Navigation Satellite System (GNSS) position. This will result in the FMC dropping that GNSS from that FMC's navigation solution and that navigation solution starts to drift in the absence of radio navaid measurements. If the GNSS position again becomes nominal, the associated FMC may continue to reject nominal GNSS measurements when the Horizontal Integrity Limit (HIL) received from the GNSS is very low. The result can be a VERIFY POS: FMC-FMC message with increasing ANP.

Status

Boeing and GE are monitoring these events as the root cause has yet to be determined.

Interim Action

If an operator experiences a similar issue, please send the BITE, QAR and flight plan data to Boeing to support this investigation.

Mitigation via Control Display Unit (CDU), which aligns closely with the 'FMC Navigation Check' Supplementary Procedure outlined in the FCOM:

1. Accessing the POS SHIFT page (and the POS REF page for additional information)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 7E994

2. Determine which FMC (FMC-L or FMC-R) is displaying the smallest position (distance) offset. (Data offset is measured from FMC-L or FMC-R to the consolidated FMC position on the POS REF page.)
3. Select the LSK for the FMC with the smallest offset on the POS SHIFT page.
4. The EXEC button will light.
5. Select EXEC.

This process will “reset” the divergent FMC allowing it to accept the GPS from the associated MMR again.

Final Action

Final actions/corrections are TBD pending completion of Root Cause/Corrective Action (RCCA) determination.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established:TBD
Solution Selected:TBD
Production Incorporation: TBD
Service Bulletin Available: TBD

Related Categories

- Significant Technical Flight Interruptions : Issues that cause in-flight events such as rejected takeoffs, air turnbacks, diversions, emergency landings, in-flight shutdowns, and abnormal stops

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 7E994