FLEET TEAM DIGEST

737MAX-FTD-35-17001

Issue Title : Crew Oxygen Cylinder Interchangeability

Airplane Model	ATA	Minor Model(s)
737MAX	3510-00	-8
Other Model(s)	**ECCN**	
737NG	9E991	

Originated Date	Last Revised Date	Created On
05/23/2017	11/20/2017	11/15/2017
Estimated Completion Date	**Next Update Date**	

Revision Description

This FTD article has been revised to provide the release date of Service Bulletin (SB) 737-35-1163, which occurred on November 1, 2017.

Parts will be available on December 8, 2017 as stated in the SB.

This FTD is now closed.

Applicability

737 MAX model airplanes line position 6561 and subsequent.

Description

On the 737NG, Boeing incorporated a design change to the crew oxygen cylinder support structure and installed the composite oxygen cylinder, P/N 806835-01, on airplanes at line position 5110 and subsequent, per PRR 39084. The installation included a band clamp, P/N BACC10FY094SE (NE10338-094), which is installed in conjunction with oxygen cylinder, P/N 806835-01. The band clamp is used in conjunction with the cylinder support structure to retain the cylinder in place. This differs from the previous oxygen cylinder support structure, which included conical brackets and a strap with a T-bolt that secured the cylinder in place.

Boeing learned that clamp, P/N BACC10FY094SE, does not allow for the installation of crew oxygen cylinder, P/N B42365-1, due to differences in the diameter of these oxygen cylinders. Cylinder, P/N B42365-1, has a slightly larger diameter than cylinder, P/N 806835-01. As a result, airplanes delivered at line position 5110 and subsequent cannot accept installation of oxygen cylinder, P/N B42365-1.

In addition, it has been noted by an operator that servicing the cylinder using BAC10FY094SE band straps can be challenging due to spatial constraints. The new design will address this issue as a product improvement by incorporating a new set of conical brackets and strap that will provide an oxygen cylinder servicing interface equivalent to what existed prior to implementation of PRR-39084.

The 737 MAX aircraft also has the same installation restrictions on aircraft LN 6561 and subsequent.

Background

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing installed oxygen cylinder assembly, P/N B42365-1, as the Boeing standard crew oxygen cylinder on the 737NG airplanes delivered after January 2002. Most operators replace the crew oxygen cylinders to replenish the oxygen, unless the airplanes were equipped with a crew oxygen cylinder fill panel. For operators with 737NG fleets that contain airplanes delivered before and after line position 5110 that also replace the crew oxygen cylinders for oxygen replenishment, spare oxygen cylinder B42365-1 may be the most commonly available spare crew oxygen cylinder.

P/N B42365-1 and P/N 806835-01 are composite oxygen cylinders. Steel oxygen cylinder P/N 801307-00 has the same diameter as P/N 806835-01, and can be installed in place of P/N 806835-01 with no additional hardware changes.

Status

Boeing has developed a conical support ring design that will provide an oxygen cylinder servicing interface equivalent to what existed prior to implementation of PRR 39084. The new flight crew oxygen cylinder support solution will accommodate all existing 737 fleet oxygen cylinders (steel and composite) without requiring retrofit of cylinder support structure.
The new conical support ring design was incorporated in production on Line Number (LN) 6562.

Service Bulletin 737-35-1163 was released on November 1, 2017.

Parts will be available on December 8, 2017 as stated in the service bulletin.

Interim Action

A conditional interchangeability statement has been added to engineering drawings to allow for interim replacement of cylinder and clamps on airplanes after line position 5110. The statement advises that for airplanes with the new oxygen cylinder support structure, installation of oxygen cylinder, P/N B42365-1, can be accomplished with the installation of two band clamps, P/N BACC10FY095SE. Each band clamp includes three rubber pads that are wrapped around the band clamp to secure and protect the oxygen cylinder. These pads should be retained and installed with the band clamps on the airplane. The pad part numbers are BACP13B6-021 (2.1 inch), BACP13B6-042 (4.2 inch), and BACP13B6-120 (12 inch).

The band clamps must be replaced if the oxygen cylinders are interchanged, since cylinder P/N 806835-01 cannot be installed with P/N BACC10FY095SE clamps; and oxygen cylinder P/N B42365-01 cannot be installed with P/N BACC10FY094SE clamps.

Final Action

Boeing has developed conical support rings that can accommodate installation of any of the oxygen cylinders currently listed in the Illustrated Parts Catalog (IPC) as directly interchangeable.
The new conical support ring design was incorporated in production on Line Number (LN) 6562.

Service Bulletin 737-35-1163 was released on November 1, 2017.

Parts will be available on December 8, 2017 as stated in the service bulletin.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Define Solution: 22-JUN-16 (complete)

Validate Solution: 25-JAN-17 (complete)

Create Part Demand: 09-MAR-17 (complete)

Production Incorporation: 01-NOV-17 (complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Service Bulletin Release: 01-NOV-17 (complete)

Parts Available for Order: 08-DEC-17

Operator Action

For 737 MAX operators with airplanes line position 6561 and subsequent who lack sufficient spare oxygen cylinder P/N 806835-01, installation of oxygen cylinder P/N B42365-1 can be accomplished with the installation of two band clamps, P/N BACC10FY095SE.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Production Revision Record (PRR)	39084		
Aircraft Maintenance Manual (AMM)	12-15-21-600-801		
Service Bulletin (SB)	737-35-1163	Original	11/01/2017

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Oxygen Cylinder Assembly		Zodiac/AVOX	801307-00
Oxygen Cylinder Assembly		Zodiac/AVOX	806835-01
Oxygen Cylinder Assembly		Carleton Technologies	B42365-1

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

Attachments:

a) Crew Oxygen Cylinder Support

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991