FLEET TEAM DIGEST

737MAX-FTD-36-18001

Issue Title : Bleed System Duct Pressure Oscillations

Airplane Model	ATA	Minor Model(s)
737MAX	3600-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
05/04/2018	02/08/2019	10/24/2018

Estimated Completion Date	Next Update Date

Revision Description

The Status and Milestones sections have been revised to advise of the cancellation of PRR 3M0149 and creation of new PRR 3M0149-1 to cover expanded IASC software scope.

The References section was revised to add PRR 3M0149-1 and FTD article 737MAX-FTD-36-19001.

This FTD article has been closed.

Future updates on this subject will be provided in FTD article 737MAX-FTD-36-19001 "Integrated Air Systems Controller (IASC) Software Improvement".

Applicability

All 737MAX airplanes prior to line number 7313.

Description

During flight test and in service, the 737-8 exhibited bleed system duct pressure oscillations.
These oscillations were observed with takeoff or climb thrust settings with Engine or Wing Anti-Ice ON or OFF. The oscillations have also been observed at reduced thrust settings with Engine Anti-Ice ON and Wing Anti-Ice OFF. During the oscillations, the left and right needles on the Dual Duct Pressure Indicator, located on the forward overhead panel, fluctuate approximately +/- 10 psig out of phase with one another. This condition does not have any adverse effects on aircraft systems.

Status

The oscillations are caused by unanticipated interaction of both the engine bleed air valves and the electronically controlled Flow Control Valves (eFCV).
Boeing and Honeywell have identified root cause and are currently developing a software change to be incorporated in the Integrated Air Supply Controller (IASC) to address these oscillations.

PRR 3M0149 was initiated for this purpose.

The IASC software change package has since been expanded to address nuisance faults discovered in the MAX fleet and lessons learned from 737NG eFlow airplanes (e.g.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

cabin rate of climb).

As a result, PRR 3M0149 has been cancelled and replaced by PRR 3M0149-1.

The expanded software package will be tracked in FTD article 737MAX-FTD-36-19001.

Interim Action

Boeing issued Service Letter (SL) 737-SL-36-039 and Operations Manual Bulletin (OMB) TBC-10 R1 to inform 737MAX operators of bleed system duct pressure oscillations that may occur in flight and that a solution is currently in work. The SL advises operators not to take maintenance action if they receive a pilot report of bleed pressure oscillations. The OMB states that if bleed pressure oscillations are observed, no crew action is needed.

Interactive Fault Isolation Manual (IFIM) Task 36-10-00-810-832 was incorporated to the IFIM to address bleed pressure oscillations. The IFIM Task advises that no maintenance is necessary, unless a maintenance message was triggered.

Final Action

Incorporate updated IASC software to production.

Release supplier service bulletin to load updated software to IASC.

Milestones

PRR 3M0149 Change Committed: June 2018 (complete)

PRR 3M0149 Cancelled: 05-DEC-2018 (complete)

PRR 3M0149-1 Change Committed: 30-JAN-2019 (complete)

Refer to FTD article 737MAX-FTD-36-19001 for production incorporation, service bulletin availability, and parts availability dates.

Operator Action

If operators receive a pilot report of bleed system duct pressure oscillations, operators are advised not to take maintenance action.

Part Information

This software change will roll the IASC part number (P/N) from P/N 51090322-002 to P/N 51090322-003.

Supplier Information

HONEYWELL ASCa INC

3333 UNITY DR

MISSISSAUGA, ON L5L 3S6 CANADA

CAGE Code: 07217

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-36-19001		
Production Revision Record (PRR)	3M0149-1		
Operations Manual Bulletin (OMB)	TBC-10	1	12/08/2017
Fault Isolation Manual (FIM)	Task 36-10-00-810-832		
Production Revision Record (PRR)	3M0149		
Service Letter (SL)	737-SL-36-039		01/05/2018

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Integrated Air Supply Controller		Honeywell	51090322-002

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- New Equipment : Information on new parts available now or soon to be introduced

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991