FLEET TEAM DIGEST

737MAX-FTD-32-17025

Issue Title : Potential Chafing Between the Left Main Landing Gear Shimmy Damper Hydraulic Return Line and a Brake System Hydraulic Hose

Airplane Model	ATA	Minor Model(s)
737MAX	3241-00	-7, -8, -9
Other Model(s)	**ECCN**	
737NG	9E991	

Originated Date	Last Revised Date	Created On
05/18/2017	09/19/2018	08/27/2018
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated to reflect proper hydraulic tube interchangeability in the Final Action section.

Applicability

All 737-7/-8/-9 aircraft prior to L/N 6780.

Description

In recent years, several 737 operators have reported occurrences of interference between the P/N 272A6101-501 shimmy damper return hydraulic tube and the P/N BACH8A04EE0320B brake No. 2 hydraulic hose common to the left hand main landing gear. This interference may eventually lead to chaffing and subsequent external leakage from the impacted hydraulic tube, as shown in the "Shimmy Damper Return Tube Chaffing" attachment.

NOTE: The right hand main landing gear shimmy damper return tube has a different routing, which precludes it from similar interference/chaffing conditions.

Status

Boeing initiated a design change in early March 2017 to mitigate the potential for future chaffing between the shimmy damper return tube and the brake No. 2 hose common to the left hand main landing gear. A new hydraulic tube (P/N 272A6101-507) was developed to allow for greater clearance from the brake system hydraulic hose on 737 MAX aircraft. This tube design improvement was committed within the 737 production system and incorporated on 737 MAX production aircraft starting at L/N 6780 (in January 2018).

Major milestones for the process are provided in the MILESTONES section, below, recognizing that they may require adjustment as the work progresses.

Interim Action

Not Applicable.

Final Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

As stated above, Boeing incorporated the improved shimmy damper return tube in 737 MAX production on L/N 6780 in January 2018. Boeing recommends that operators remove and replace in-service shimmy damper return tubes on an attrition/on-condition basis.

The new P/N 272A6101-507 hydraulic tube is a two-way interchangeable replacement for the P/N 272A6101-501 hydraulic tube.

Furthermore, Boeing made the new P/N 272A6101-507 hydraulic tube the preferred spares component for in-service aircraft. This interchangeability is reflected in the 15-MAY-2018 revision of the 737 MAX IPC.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 01-MAR-2017 (Complete)

Solution Selected: 14-MAR-2017 (Complete)

Change Committed: 20-APR-2017 (Complete)

Production Incorporation: 09-JAN-2018 (Complete, L/N 6780)

Service Documents Available: 15-MAY-2018 (Complete)

Operator Action

As stated previously, Boeing recommends that operators remove and replace in-service damaged P/N 272A6101-501 shimmy damper return tubes on an attrition/on-condition basis with the improved P/N 272A6101-507 tube.

In the event that an new P/N 272A6101-507 is unavailable for installation, Boeing recommends that operators experiencing interference between the left shimmy damper tube and the brake No. 2 hose perform the following:

1. Inspect the P/N 272A6101-501 hydraulic tube for chaffing damage. If chaffing depth is present, but the damage is within the limits provided below, then the tube may remain in-service.

- Chafed - 0.006 in./Dent - 0.005 in.

If chaffing depth is outside the limits provided above, then the tube must be replaced. NOTE: Boeing will update AMM Task 20-10-51-300-801 to reflect the damage limits provided above in the 15-MAY-2018 revision of the 737 MAX AMM (an AMM Temporary Revision is currently available on MyBoeingFleet).

2. Apply spiral wrap in order to protect the left shimmy damper hydraulic tube from chafing damage. Panduit (P/N T25F-C0) weather-resistant polyethylene 0.25 inch diameter spiral wrap is a suitable product; as is Ark-Plas (P/N AP01SW24BK or AP01SW25BK) UV-resistant polyethylene wrap or (P/N AP01NSW25N) nylon wrap.

Panduit Website: www.panduit.com

Ark-Plas Website: www.ark-plas.com

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

NOTE: Boeing has no objection to the utilization of spiral wrap to protect the left shimmy damper hydraulic tube; however, operators will need to coordinate the incorporation of spiral wrap with their local regulatory agency.

3. Perform an inspection of the hose installation in order to verify that the hoses are not twisted, which could result in the hose making contact with adjacent parts. Boeing also recommends the following: a) When tightening hose B-nuts, it is imperative to use two wrenches: one on the B-nut to tighten it and another on the smaller set of wrench flats on the hose body next to the B-nut to prevent the hose from twisting during installation, b) Verify that the angled elbow fitting at the upper end of the hose are pointed directly forward within plus/minus 5 degrees and that the elbow fitting on the brake is pointed straight forward to 10 degrees away from the wheel (see the "Elbow Clearance Requirements" attachment for additional details).

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Illustrated Parts Catalog (IPC)	32-32-51-03, item 95		05/15/2018
Illustrated Parts Catalog (IPC)	32-41-52-01, Item 50		03/15/2017
Fleet Team Economic (FTE)	FTE-32-14024		11/30/2014
Drawing	272A6101		
Aircraft Maintenance Manual (AMM)	TASK 20-10-51-300-801		03/15/2017
Drawing	274A1900		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Hydraulic Tube - Shimmy Damper Return (Improved Part)	272A6101-507		
Hydraulic Tube - Shimmy Damper Return	272A6101-501		
Hydraulic Hose - Brake No. 2	BACH8A04EE0320B		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board
- In Service Occurrences : null

Attachments:

a) Shimmy Damper Return Tube Chaffing

b) Elbow Clearance Requirements

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991