FLEET TEAM DIGEST

737MAX-FTD-32-17026

Issue Title : Hydraulic Leaks Due to Fracture of Brake Fuse Reset Lever Screws

Airplane Model	ATA	Minor Model(s)
737MAX	3241-72	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737, 737NG	9E991

Originated Date	Last Revised Date	Created On
06/28/2017	06/28/2017	04/21/2017

Estimated Completion Date	Next Update Date

Applicability

All 737MAX airplanes.

Description

Boeing has received a number of reports of hydraulic leaks on 737NG airplanes that were attributed to fractures of the P/N NAS1352-06H4P (CMM 32-40-18, Item 5) reset lever attachment screws on the Boeing P/N 10-62204-17 (Triumph P/N 2-8041-1) hydraulic fuses (IPC 29-21-52-05, Item 565) installed in the normal brake system. There have not been similar reports of screw fractures on the same part number fuses installed in the alternate brake system.

Hours/Cycles

All cases of screw fracture/leakage have occurred after accumulating between 8,500 and 21,000 flight hours and 4,500 to 21,000 flight cycles.

Background

Boeing and Triumph Actuation Systems, the fuse supplier, have examined several fuses with fractured reset lever attachment screws to identify the root cause of the fractures. Both Triumph and Boeing have independently confirmed that the screws are fracturing due to fatigue (no contribution due to corrosion, abuse, over-torque or overload). The root cause of the premature fatigue fractures has not been identified.

Status

n/a

Interim Action

n/a

Final Action

A design solution is not available.

Operator Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing recommends that operators request their fuse service supplier replace these screws at every shop visit. This will help remove high cycle screws from service and reduce the chance of in-service failures due to fatigue. If operators are performing fuse replacements per the MPD interval, this would be a good time to replace these screws.

We also have no objection if operators choose to initiate a fleet campaign to replace the attachment screws in-situ on the airplane prior to scheduled fuse removals per MPD requirements. Most reported screw fractures have occurred at 10,000 cycles or greater, so we would suggest performing such an action at an interval that is about half the interval of the MPD limit. If an operators chooses to replace the screws in-situ, we suggest that they replace the screws one at a time using the instructions in Triumph Actuation Systems CMM 32-40-18 and Boeing AMM 32-41-72.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Component Maintenance Manual (CMM)	32-40-18 Triumph Actuation Systems		
Illustrated Parts Catalog (IPC)	29-21-52-05		
Aircraft Maintenance Manual (AMM)	32-41-72		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Fuse - Hydraulic Brake	10-62204-17	Triumph Actuation Systems	2-8041-1
Cap Screw			NAS1352-06H4P

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- In Service Occurrences : null

Attachments:

a) Fuse With Lever Separated

b) Brake Fuse Screw Fractures

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991