FLEET TEAM DIGEST

737MAX-FTD-32-17027

Issue Title : Tire and Brake Monitoring Unit Nuisance Maintenance Messages

Airplane Model	ATA	Minor Model(s)
737MAX	3246-00	-8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
07/14/2017	03/26/2018	02/23/2018
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated status and closed article.

Applicability

737MAX airplanes equipped with the optional Tire Pressure and/or Brake Temperature Monitoring System (TBMS) with line numbers prior to 6740 (except line numbers 5668, 5728, 6250, and 6308 which received the fix out of sequence during production).

Description

There have been several reports of certain Maintenance Messages intermittently occurring on the TBMS. The messages, accessible from the Multifunction Display or from a maintenance laptop, are as follows:

32-40005: TBMU (BRAKE TEMPERATURE) HAS NO INPUT FROM ADIRU-L ON ADIRU ARINC 429 BUS

32-50005: TBMU (TIRE PRESSURE) HAS NO INPUT FROM ADIRU-L ON ADIRU ARINC 429 BUS

To date, these Maintenance Messages have all been inactive when discovered. Also, these Maintenance Messages are not correlated with any system Status messages and therefore have no flight deck effects (FDEs).

Background

The TBMS uses a left ADIRU ground speed signal to inhibit illumination of the BRAKE TEMP light or the TIRE PRESS light in the flight deck during critical high speed portions of a takeoff. The Tire and Brake Monitoring Unit (TBMU) monitors the left ADIRU signal and sets fault(s) if the signal is considered invalid, resulting in Maintenance Messages 32-40005 and/or 32-50005.

In all cases to date, the TBMS functioned normally even when these Maintenance Messages were stored. As such, Boeing considers these as nuisance messages.

Status

Fix identified. See Final Action.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

See Operator Action below.

Final Action

Boeing has developed a fix for these nuisance messages by revising the Onboard Network Systems (ONS) Loadable Health Attribute (LHA) software to inhibit messages 32-40005 and 32-50005.
Network File Server OMF OSS software part number BCG3F-0MFC-0001 (or later versions that may be developed) contain this fix.

737 MAX airplanes line number 6740 and-on contain LHA software that resolves this issue.

Also, line numbers 5668, 5728, 6250, and 6308 received the fix out of sequence during production.

Operator Action

For airplanes using the earlier LHA software:

If Maintenance Messages 32-40005 and/or 32-50005 are displayed as 'not active' and there are no system Status messages associated with TBMS, Boeing considers the faults as nuisance and can be ignored. Note that the faults can be cleared at any convenient maintenance opportunity.

If these Maintenance Messages are 'active' and there are no system Status messages associated with TBMS, it is acceptable to dispatch the airplane (the TBMS remains functional in these cases). The fault(s) can be troubleshot at a convenient maintenance opportunity per existing IFIM procedures.

As noted above, these maintenance messages are inhibited in later versions of LHA software.

Part Information

Software version BCG3F-0MFC-0001 is currently available through Boeing Spares.

The software will be delivered via the Boeing Electronic Distribution of Software (BEDS).

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Tire and Brake Monitoring Unit (TBMU)	S277A501-101	Crane	83-154-01
OMF OSS software	BCG3F0MFC0001	Boeing	BCG3F-0MFC-0001

Related Categories

- High Occurrence Maintenance Message : null
- In Service Occurrences : null

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991