# FLEET TEAM DIGEST

## 737MAX-FTD-32-21003

**Issue Title :** 737MAX Nose Wheel Steering Swivel Valve Sealant

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3251-11 | -7, -8, -8200, -9, -BBJ |

| Other Model(s) | ECCN |
|---|---|
| | 9E991 |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 08/12/2021 | 08/12/2021 | 04/30/2021 |

| Estimated Completion Date | Next Update Date |
|---|---|
| | |

## Applicability

All 737MAX aircraft

## Description

Boeing has received reports of sealant deterioration on the Nose Landing Gear (NLG) steering swivel valve assembly P/N: 521800-1001 at the location shown in the attachment. This Fleet Team Digest (FTD) informs operators of a design change that eliminates a portion of sealant application on the swivel valve assembly. New manufactured swivel valve assemblies will no longer have seals this location.

Additionally, Boeing has received operator reports of swivel valve leakage or that the valves have displayed "weepage" at the upper and lower dynamic seals between the swivel valve sleeve and rotating spooling after extended low pressure inactivity. Please refer to "Interim Action" portion of this FTD article for troubleshooting and corrective action.

## Background

Boeing conducted an investigation of parked airplanes for swivel seal degradation or signs of "dis-bonding" from the swivel sleeve body and with supplier coordination, concluded the seals were not necessary and did not prevent any ingress of fluids or affected the performance of the component. As such, Boeing and Parker have worked to remove the requirement to add sealant.

Additionally, Boeing inspected parked airplanes for visual signs of leakage from the NLG steering swivel assembly. Boeing concluded that swivel valve leakage was due to extended low pressure inactivity of the dynamic seals and actuating the nose wheel steering systems through a minimum of 25 cycles resolved the suspect leakage or "weepage" of the dynamic seals.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Status

Boeing has been notified by Parker that new units will not have sealant on the lowest swivels effective on parts manufactured after August 11, 2020. Parker CMM 32-50-18, Revision no. 4 was updated to also reflect this change and remove the sealant requirement at this location.

Please refer to Parker Service Information Letter (SIL) - 521800-32-001SL for additional information.

## Interim Action

If steering swivel valves are displaying leakage or "weepage", clean/wipe fluids from valve assembly, pressurize hydraulic system, and actuate the nose wheel steering system through a minimum of 25 cycles.

NOTE: To prevent tire scrub damage when actuating the steering, either disconnect the torsion link, use grease plates, or jack the airplane. Refer to AMM 32-51-00/501 (Nose Wheel Steering System –Adjustment/Test).

Inspect the area for signs of leakage. Remove hydraulic pressure, inspect the area for signs of leakage. Refer to AMM 29-00-00/ Table 601 to determine if the leakage is within limits.

## Final Action

If sealant is found to be deteriorated, Boeing can provide instructions to remove it via a service request.

Operators with additional questions regarding this change can contact their respective Parker Representative at the numbers below:

PARKER CORPORATION

14300 Alton Parkway

Irvine, CA 92618-1898

PHONE: (949) 833-3000

FAX: (949) 809-8390

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: July 2020 (Complete)

Solution Selected:July 2020 (Complete)

Change Committed: Aug 2020 (Complete)

Supplier Production Incorporation: Aug 2020 (Complete)

Parts Available: August 2020 (Complete)

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Other | Parker Service Letter: 521800-32-001SL | | |
| Component Maintenance Manual (CMM) | 32-50-18 | | |

## Parts List

| Part Name | Boeing Part Number | Supplier Name | Supplier Number |
|---|---|---|---|
| VALVE ASSY - STEERING, NLG | 521800-1001 | Parker Hannifin Corporation | |

## Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

## Attachments:

a) Swivel Fillet Seals Location Example

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991