FLEET TEAM DIGEST

737MAX-FTD-32-24002

Issue Title : 737MAX Incorrect Brake System Hydraulic Line or Wiring Routing

Airplane Model	ATA	Minor Model(s)
737MAX	3240-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
11/06/2024	12/10/2025	11/20/2025

Estimated Completion Date	Next Update Date

Revision Description

Rev 1 – Provide reference to AMM revision date(s) and latest information as of 26-Feb-2025.

Rev 2 – Update to section 'Final Action' in order to provide 737MAX AMM enhancement reference for 15-May-2025 revision release.

Rev 3 – Update to section 'Final Action' in order to provide 737MAX AMM enhancement reference for 15-Sep-2025 and 15-Nov-2025 revision releases.

Applicability

All 737 MAX airplanes that recently replaced the main landing gear, axle, brake flow limiter, or have plans to perform such actions.

Description

Boeing has identified a small number of Operators that experienced a tire burst event due to incorrect hydraulic line routing or incorrect wiring of the antiskid wheel speed transducer. When these components are improperly routed, the Antiskid Autobrake Control Unit (AACU) sends incorrect commands to the paired brake positions. This misrouting causes hydraulic lines or signals to be crossed, leading the AACU to release brake pressure from the wrong brake position during a skid condition. As a result, the brake pressure remains engaged which causes the wheel-tire assembly to lock up and sustain skid damage. In more severe cases, the skidding tire can lead to a tire burst resulting in secondary damage to adjacent structures and systems, as well as a loss of braking at the paired brake positions. The effects of this maintenance error will not manifest themselves until there is a skidding condition. Since skidding conditions are encountered sporadically depending on how the airplane is operated, the issue may manifest during the first flight cycle after the maintenance error or may not occurs until many cycles later.

Status

Boeing has identified specific Aircraft Maintenance Manual (AMM) tasks where improper maintenance may occur. Please see ref/a/ attachment showing locations where improper hydraulic brake line / wheel speed transducer wiring routing can occur.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Interim Action

In order to mitigate these events from occurring, Boeing recommends implementing the following best practices:

Hydraulic Line Installation During Landing Gear Installation

- When Performing 737MAX Pageblock 32-11-00/401 'Main Landing Gear - Removal/Installation', before removing the main landing gear for replacement, temporarily label the hydraulic lines when removing the landing gear for replacement. Once a replacement landing gear is installed, ensure the hydraulic lines are correctly routed according to 737-7/-8/-9 AMM Figure 401/32-11-00-990-802 item [6] or 737-10 AMM Figure 406/32-11-00-990-808 item [6] as well.

Antiskid Wheel Speed Transducer / Wire Harness

- Make sure that you attach a label to the wires to indicate the left and right connectors, when disconnecting the wires.
- Make sure that you connect the correct wires to the correct wheel speed transducer connector or in-axle assembly.

Brake Flow Limiter

- When performing 737MAX Pageblock 32-41-96/401 '*Brake Flow Limiter - Removal/Installation*', before disconnecting the lines, temporarily label the hydraulic lines to the corresponding brake positions. Once the brake flow limiter is installed, ensure the hydraulic lines are correctly routed per 737-7/-8/-9 AMM Figure 401/32-41-96-990-801 detail view [B] or 737-10 AMM Figure 402/32-41-96-990-802 detail view [B] , which shows the lines from the rear spar to the landing gear support beam, and the flexible hoses connecting to the flow limiters.

Airplane Level Functional Check

- Perform 737MAX AMM Task 32-42-00-720-803 '*Antiskid Valve Operational Test*', to ensure the selected brake position has its antiskid valve releasing/receiving brake pressure when commanded by the AACU.
- Perform 737MAX AMM Task 32-42-00-710-803 '*Transducer Operational Test*', to ensure the respective wheel position has its antiskid wheel speed transducer wired correctly to the AACU.

NOTE: If an Operator is experiencing tire damage or worn tires, Boeing recommends performing 737MAX Interactive Fault Isolation Manual (IFIM) 32-42-00-810-801 (left outboard tire), or 32-42-00-810-802 (right outboard tire), or 32-42-00-810-803 (left inboard tire), or 32-42-00-810-804 (right inboard tire), called '*Tire Damage or Worn - Fault Isolation*', to isolate the component(s) that is contributing to the incident. The IFIM makes reference to 737MAX AMM 05-51-16 '*Flat Spotted Tires*', which contains instructions to perform an antiskid valve operational test and transducer spin test.

Final Action

Boeing has evaluated several AMM tasks to determine which of them need to be updated to include additional 'Warning' and 'Caution' statements aimed at preventing improper routing of hydraulic lines and antiskid wiring. In addition, Boeing has clarified and included additional operational checks in the AMM to ensure once the installation is complete, the routing of any disturbed hydraulic lines and/or wiring is correct before releasing the airplane for operation.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The following 737MAX AMM enhancement have been completed:

- 15-Sep-2024 Revision Date
  - AMM Task 32-11-00-400-802 - MLG Installation, added step to do the antiskid valve operational test per AMM Task 32-42-00-720-803.
  - AMM Task 05-51-16-210-801 - Flat Spotted Tires Inspection, added step to do the antiskid valve operational test per AMM Task 32-42-00-720-803.
- 15-Jan-2025 Revision Date
  - AMM Task 32-41-96-400-801 - Brake Flow Limiter Installation, added steps to prevent and detect possible cross connections of hydraulic tubing that are re-connected during this task
  - AMM Task 32-42-00-720-803 - Antiskid Valve Operational Test, enhanced AMM procedure to remove any ambiguity with the intent of this AMM task
- 15-May-2025 Revision Date
  - AMM Task 32-42-00-710-801 - Transducer Functional Test, standardize all four tests (warnings, wording, chapters) while preserving the specific differences between them, divide the “Antiskid Transducer Pair Wheel” table while maintain the same instructions, include the requirement for one person to be present at the main landing gear brakes and changed the instructions phrasing to “observe the movement of the brake piston or wear pins”.
- 15-Sep-2025 Revision Date
  - AMM Task 32-11-85-420-801 - Main Landing Gear Axle Installation, added information to perform antiskid valve operational test before transducer test.
  - AMM Task 32-41-00-710-803 - Alternate Brake System - Operational Test, added instructions to remove hydraulic power from the airplane, depress the brake pedals a minimum 12 time to remove hydraulic pressure from the brake accumulator, and activate only System A hydraulics (alternate source) with detail instructions for one person to confirm the brakes are moving when commanded.
  - AMM Task 32-42-00-710-803 - Transducer Operational Test, contains information to observe the movement of the brake pistons or wear pins to make sure that the selected brake releases and then applies again
  - AMM Task 32-42-00-720-803 - Antiskid Valve Operational Test, which contains information related to a person must be at the Main Landing Gear (MLG) brake area to monitor the movement of the brake pistons or wear pins. This is to make sure that the correct brake releases and engages.
- 15-Nov-2025 Revision Date
  - AMM Task 32-41-41-400-801 - Main Landing Gear Brake Installation, added a note that states: If the brake wear pins move, the brakes will release.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Aircraft Maintenance Manual Revision Date: 15-Sep-2025

Aircraft Maintenance Manual Revision Date: 15-Nov-2025

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Other	a) Improper hydraulic line / wiring routing		
Service Related Problem (SRP)	b) 737NG-SRP-32-0257		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

Attachments:

a) Improper hydraulic line / wiring routing

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991