FLEET TEAM DIGEST

737MAX-FTD-33-22001

Issue Title : Tailcone Anti-Collision and Aft Position Light Moisture Ingress Condition

Airplane Model	ATA	Minor Model(s)
737MAX	3300-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
06/10/2022	06/10/2022	06/03/2022

Estimated Completion Date	Next Update Date

Description

The 737MAX incorporated a new tailcone design where new Tailcone Anti-Collision and Aft Position Lights (TCAPL) are installed on each side of the tailcone. The part number of this assembly is P/N 84091-1. This article provides guidance and information if moisture is observed inside the light assembly.

Status

The Tailcone Anti-Collision and Aft Position Light Assembly is designed and qualified to operate under all foreseeable airplane operating conditions including exposure to high humidity, salt fog, rain, icing, etc. Condensation on the inside lens surface is considered to be normal and is expected since these lights are not hermetically sealed and have a drain hole incorporated within them to drain any accumulated moisture outboard. Water/moisture condensation visible on the inside lens surface is normal/ acceptable and no maitenance action need to be taken.

However, significant water/fluid accumulation/buildup inside the light is not normal since this is an indication that the drain hole at the bottom of the light may be blocked/plugged with debris and should be cleared out. If this condition is observed, it is recommended to inspect if the drain hole on the light assemly is either plugged or blocked by debris. See attachment for the location of the drain hole.

Minor water/fluid accumulation at the bottom of the light due to natural moisture condensation is acceptable and should be drained out during takeoff due to the pitch up angle of the airplane which places the light drain hole at its lowest position to allow any minor water accumulation to drain outboard.

Interim Action

None, information only.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

None, information only.

Milestones

None, information only.

Related Categories

- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

Attachments:

a) Drain Hole

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991