FLEET TEAM DIGEST

737MAX-FTD-33-22002

Issue Title : Generation 3.3 BSI Sidewall Lighting Upgrade

Airplane Model	ATA	Minor Model(s)
737MAX	3300-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
12/19/2022	07/28/2026	04/17/2026

Estimated Completion Date	Next Update Date
12/31/2026	10/31/2026

Revision Description

Updated Status, Final Action, and Milestones

Applicability

All 737 MAX airplanes

Description

Operators have experienced low reliability and a high number of Generation 1 and 2 Sidewall Lights failures and removals. The top drivers for removals are related to the power supply board, and the root cause has been found to be the reliability of key components in the control circuitry. Collins is in development of a Generation 3.3 sidewall lighting upgrade to address the reliability issues.

Status

Part qualification testing of the Generation 3.3 Sidewall Lights was completed by Collins Aerospace in October 2025.

The first 737 MAX airplane installed with the new sidewall light assemblies is Line Number 9534, delivered in May 2026.

Certification of the Generation 3.3 Light Assemblies is phased per minor model and configuration with the following date targets:

- 737-8 Configurations – May to June 2026 (Complete)
- 737-8200 Configurations – June to October 2026 (Target)
- 737-9 Configurations – May to August 2026 (Target)

Collins Service Letter 33-0022 was published to provide a release notice for the Generation 3.3 lights.

Boeing Service Letter 737-SL-33-102 will be published to inform operators of BSI Lighting Generation 3.3 improvements. ECD August 2026.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Fault Isolation Manual (FIM) revisions are in-work to provide improved troubleshooting steps for inoperative lights and data loading faults. ECD Q4 2026.

BSI Lighting videos are also in development to supplement the AMM and FIM. Boeing is planning to release video modules in batches:

- Two System Overview Modules was released. An third module is planned for release in August 2026
- Maintenance and Troubleshooting Modules to be released by Q1 2027

Interim Action

Boeing updated the Dispatch Deviations Guide (DDG) to allow dispatch with greater than 40% of sidewall LED lights inoperative provided that photoluminescent strips charging criterias are followed (Released April 2024).

Final Action

The Generation 3.3 Sidewall Lighting redesign is intended to improve the reliability of the Sidewall Lights. This upgrade introduces new part numbers for the BSI Sidewall Lights and the Over-Wing Exit Lights. Refer to the Parts List section for the Generation 3.3 Part Numbers. Operators can now place an order for these parts through Boeing Spares.

Interchangeability Information:

- Generation 2 Lights can be used as spares to Generation 3.3 Lights
- The interchangeability of the Generation 2 to Generation 3.3 Lights will be updated to qualified two-way interchangeable as certification is completed on the minor models.
  - The Generation 2 to Generation 3.3 Lights are currently two-way interchangeable for the following configurations: All 737-8 airplanes and 737-8200 airplanes with Space Bins.
  - Boeing recommends using Generation 3.3 Lights as spares for these airplanes and use Generation 2 Lights on airplanes that have not yet been certified to use Generation 3.3 Lights.

The lighting upgrade incorporates new technology LEDs, reduce the quantity of internal power supplies, improve field repairability, introduce loadable light software capability, and reduce the weight of assembly.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: January 2022 (Complete)

Solution Selected: May 2022 (Complete)

Qualification Testing Completion: October 2025 (Complete)

Production Incorporation of Gen 3.3 Lights: May 2026 (Complete)

Collins Service Letter: July 2026 (Complete)

Systems Overview Videos: August 2026 (Target)

Boeing Service Letter: August 2026 (Target)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

FIM Updates: Q4 2026 (Target)

Maintenance and Troubleshooting Videos: Q1 2027 (Target)

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
SIDEWALL LIGHT 14", TYPE A		Collins Aerospace	9654-14-0000
SIDEWALL LIGHT 14", TYPE B		Collins Aerospace	9654-14-0001
SIDEWALL LIGHT 14", TYPE C		Collins Aerospace	9654-14-0002
SIDEWALL LIGHT 14", TYPE D		Collins Aerospace	9654-14-0003
SIDEWALL LIGHT 14", TYPE E		Collins Aerospace	9654-14-0004
SIDEWALL LIGHT 14", TYPE F		Collins Aerospace	9654-14-0005
SIDEWALL LIGHT 26", TYPE B		Collins Aerospace	9654-26-0004
SIDEWALL LIGHT 26", TYPE D		Collins Aerospace	9654-26-0001
SIDEWALL LIGHT 26", TYPE E		Collins Aerospace	9654-26-0002
SIDEWALL LIGHT 26", TYPE F		Collins Aerospace	9654-26-0003
SIDEWALL LIGHT 35", TYPE A		Collins Aerospace	9654-35-0000
SIDEWALL LIGHT 35", TYPE B		Collins Aerospace	9654-35-0001
SIDEWALL LIGHT 35", TYPE C		Collins Aerospace	9654-35-0002
SIDEWALL LIGHT 35", TYPE D		Collins Aerospace	9654-35-0003
SIDEWALL LIGHT 35", TYPE E		Collins Aerospace	9654-35-0004
SIDEWALL LIGHT 35", TYPE F		Collins Aerospace	9654-35-0005
OVERWING EXIT LIGHT, TYPE B		Collins Aerospace	9704-14-0000
SIDEWALL LIGHT 26", TYPE A		Collins Aerospace	9654-26-0000
OVERWING EXIT LIGHT, TYPE F		Collins Aerospace	9704-14-0001

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991