# FLEET TEAM DIGEST

## 737MAX-FTD-29-24001

**Issue Title :** 737 MAX Hydraulic Quick Disconnect

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 2910-00 | -8, -8200, -9 |
| **Other Model(s)** | **ECCN** | |
| | 9E991 | |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 03/26/2024 | 10/30/2026 | 05/28/2026 |
| **Estimated Completion Date** | **Next Update Date** | |

## Revision Description

Boeing has incorporated the improved quick disconnect hose and fittings into production.

## Applicability

737 MAX

## Description

Boeing has received feedback that ensuring the proper installation of the Quick Disconnect (QD) at the engine pylon/strut is difficult on the 737 MAX due to the fire sleeve and pylon fairing obscuring the Quick Disconnect (QD) sleeve and lock tab. Additionally, it may be possible for maintenance personnel to assume that the QD has been fully tightened, but could have over rotated the QD collar, past the lock tab. This condition has to be recognized by maintenance personnel, as the over rotated condition requires loosening of the QD collar and then re-tightening to match the lock tab. To achieve proper installation, the lock tab needs to be secured into the lock slot.

## Background

Boeing has in-service reports associated to hydraulic restrictions created by improper QD installations. Examples of failures associated with the quick disconnect fittings have resulted in EDP failure (overheat), including a scenario where an EDP fails with hydraulic fluid contaminating the accessory gearbox, resulting in a commanded in-flight shutdown of the engine.

Boeing mentions, the 737NG and 737 MAX hydraulic quick disconnect fittings are similar in how to lock the QD fitting. Where the 737MAX design differs, is that the 737MAX incorporates a fire sleeve over the hydraulic quick disconnect fitting at the pylon location, thus ensuring the proper installation at the engine pylon/strut can be difficult. Furthermore, functional/operation checks may not identify anomalies created by QD restrictions.

## Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

Boeing evaluated the hydraulic quick disconnect design, to improve and help mitigate human factors associated to assuring proper installation of the quick disconnect. This improvement no longer allows an overturn of the QD rotating sleeve, pass the lock tab. The clocking of rotating sleeve now stops at the lock tab of the mating fitting, enabling it to snap into the slot.

## Interim Action

Boeing recommends ensuring that the quick disconnects are properly installed by verifying that the locking tabs are fully engaged into the locking slot per reference c)  AMM TASK 71-00-02-410-007-G00.

Boeing has confirmed the use of a borescope to validate the proper pylon QD installation, this may require inserting the borescope between the strut fire blanket and the pylon fitting.

In addition, Boeing encourages operators to implement the reference a) training video into custom training for mechanics, the “Hydraulic Hose Quick Disconnect Fittings” video is available via myboeingfleet.com under “VIDEO-MXE-02-00058” per AMM 71-00-02/401.

## Final Action

Boeing notes the part number did not change, and identifies the improved hydraulic quick disconnects with the revision level on the ID tag of the hydraulic hose,  as follows:

| Part Number | System | Rev (OLD) | Rev (New-Improved) |
|---|---|---|---|
| AE721225-12 | Pressure | C | D and on |
| AE721211-8 | Supply | A | B and on |
| AE721226-7 | Pylon Case Drain | A | B and on |
| AE721227-1 | EDP Case Drain | D | E and on |

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: NA
Solution Selected: Complete
Change Committed: Complete
Production Incorporation: Complete
Service Bulletin Available: NA
Parts Available: Available

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Aircraft Maintenance Manual (AMM) | VIDEO-MXE-02-00058 | | |
| Multi-Operator Message (MOM) | MOM-MOM-24-0013 | | |
| Aircraft Maintenance Manual (AMM) | 71-00-02-410-007-G00 | | |

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991