FLEET TEAM DIGEST

737MAX-FTD-29-26001

Issue Title : In-Flight Substitution Error Leading to Hydraulic System or Anti-Ice System Misconfiguration

Airplane Model	ATA	Minor Model(s)
737MAX	2900-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG, 737	9E991

Originated Date	Last Revised Date	Created On
06/19/2026	09/18/2026	09/16/2026

Estimated Completion Date	Next Update Date
06/16/2028	03/18/2027

Revision Description

Re-wording in description field.

Applicability

All 737 aircraft.

Description

Boeing has received multiple 737CL/NG/MAX operator reports of flight crew members inadvertently misconfiguring, or turning off, Hydraulic System A or B Pumps when intending to manipulate the Engine or Wing Anti-Ice On/Off switches in the flight deck. These cases were reviewed internally by Boeing and determined to be safety.

The Engine Anti-Ice On/Off Switches, the Wing Anti-Ice On/Off Switches, the Hydraulic Pump (Engine Driven and Electric Motor Driven) System A On/Off Switches, and the Hydraulic Pump (Engine Driven and Electric Motor Driven) System B On/Off Switches are located on the same overhead panel in all 737Classic, NG, and MAX models. These switches are all located in the same proximity and share similar tactile feel, operation, and switch lever appearance.

Multiple in-flight occurrences were observed by operators and reported to Boeing in which hydraulic system A and/or B were inadvertently/erroneously deactivated and reactivated by flight crews presumably when intending to select adjacent anti-ice system switches. This error and the resulting potential hydraulic system misconfiguration may cause increased pilot workload during certain phases of flight. Engine Anti-Ice System not being turned on as intended may result in multi-engine unrecoverable power loss in icing conditions.

Boeing has received further fleet input that suggests these types of substitution errors may be occurring more frequently than is reported to Boeing. If both the engine driven hydraulic pump and electric motor driven pump of either Hydraulic System are switched off inadvertently, an amber LOW PRESSURE light on the overhead panel will illuminate and a corresponding Master Caution Light will appear on the glareshield.

For Reference, the Hydraulic System A powers the following systems:
- Autopilot A
- Nose Gear Steering
- Landing Gear Extension and Retraction
- Power Transfer Unit

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

• Ground Spoilers
• Flight Spoilers
• Ailerons
• Rudder
• Elevator and Elevator Feel
• Left Thrust Reverser

And, Hydraulic System B powers the following systems:
• Autopilot B
• Leading Edge (LE) Flaps and Slats
• Trailing Edge (TE) Flaps
• Flight Spoilers (one on each wing)
• Ailerons
• Rudder / Yaw Damper
• Elevator and Elevator Feel
• Normal Brakes
• Right Thrust Reverser

Status

Boeing has opened Safety Service Related Problem Projects (SRPs) for the 737 Classic and 737 NG & MAX models to address this issue. After the SRP kickoff meetings, further revisions of this FTD will report milestone status, progress, and any interim and final operator actions.

Interim Action

Interim actions will be established as part of the SRP effort and provided within this section.

Final Action

To be determined through SRP Solution Selection.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

- Root Cause Established: To be determined
- Solution Selected: To be determined
- Change Committed: To be determined
- Production Incorporation: To be determined
- Service Bulletin Available: To be determined
- Parts Available: To be determined

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Drawing	69-37317		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Drawing	69-37320		
Drawing	233A3107		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
P5-8 Module Assy - Hydraulic Pump	69-37317		
P5-11 Module Assy - Engine Anti-Ice	69-37320		

Related Categories

- Flight Operations : Flight Operations
- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991