FLEET TEAM DIGEST

737MAX-FTD-30-18001

Issue Title : 737 MAX Engine and Wing Anti-Ice Nuisance Indication of COWL VALVE Light and L/R VALVE Light

Airplane Model	ATA	Minor Model(s)
737MAX	3000-00	-7, -8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
05/03/2018	05/06/2021	04/16/2021
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated the Final Action, Milestones, and Operator Action sections of this FTD article to provide status toward resolution. Moved information from the Status section into the Background section. With the release of all Service Bulletin packages, this article is now considered closed.

All changes are highlighted in blue text.

Applicability

The Engine Anti-Ice (EAI) COWL VALVE light and Wing Anti-Ice (WAI) L/R VALVE light anomalies affect 737-7, -8, and -9 airplanes prior to Line Number 7000.

Description

During 737-8 flight tests, nuisance illumination of the amber engine anti-ice COWL VALVE light(s) and amber wing anti-ice L/R VALVE light(s) occurred when engine anti-ice was used at altitudes below FL230 and wing anti-ice was used at altitudes above FL230.

Background

During 737-8 flight tests, illumination of the amber COWL VALVE light(s) occurred during use of the engine anti-ice system under the following conditions:

• Engine idle thrust during level flight for more than 1.5 minutes at altitude FL230 and below

• Selecting Engine anti-ice ON

• Total Air Temperature less than 10 degree Celsius

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Under the above conditions, the engine anti-ice COWL VALVE light(s) can illuminate for approximately 15 seconds even with sufficient air pressure available downstream of the engine cowl anti-ice valve to provide engine anti-ice protection.

Similarly, illumination of the amber wing anti-ice L/R VALVE light(s) occurred during use of the wing anti-ice system under the following conditions:

• Engine idle thrust descent above FL230

• Selecting wing anti-ice ON with engine anti-ice already in use.

Under the above conditions, the wing anti-ice L VALVE or R VALVE light can illuminate for approximately 15 seconds even with sufficient air pressure available downstream of the wing anti-ice valve to provide wing anti-ice protection.

Illumination of the engine anti-ice COWL VALVE light(s) or wing anti-ice L/R VALVE light(s) for more than approximately 10 seconds illuminates the two MASTER CAUTION lights and the amber ANTI-ICE light on the system annunciator panel.

Boeing established a production solution to address this issue under Production Revision Record (PRR) 3M0133, which removes the indication pressure switches from the wing anti-ice system on airplanes starting from Line Number 7138 and on; and additionally removes the operating pressure switches from the engine anti-ice system on airplane Line Numbers 6798, 7260, 7273, 7285, 7318, 7326, 7333, 7335, 7351, 7355, 7361 through 7366, 7370 through 7397, 7399 through 7405, 7408, 7411, 7414 through 7434, 7436 through 7461, 7464 and on.

To limit the fleet's exposure to this issue, Boeing created Production EFIX 73X-1802-0011 to cap and stow the two Air Data Inertial Reference Unit (ADIRU) left and right TAI High Altitude output discretes to the P5-11 Anti-Ice Control Panel (AICP); and connect the left and right TAI High Altitude Signals on the P5-11 AICP to DC ground. The Production EFIX 73X-1802-0011 essentially bypasses the pressure switches to resolve the engine anti-ice COWL VALVE light and wing anti-ice L/R VALVE light anomalies on airplanes starting from Line Number 7000.

To clarify further, all aircraft outside of the above-noted range (i.e. airplane Line Numbers 7138 through 7259, 7261 through 7272, 7274 through 7284, 7286 through 7317, 7319 through 7325, 7327 through 7332, 7334, 7336 through 7350, 7352 through 7354, 7356 through 7360, 7367 through 7369, 7398, 7406 through 7407, 7409 through 7410, 7412 through 7413, 7435, and 7462

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

through 7463) will have the pressure switch from the wing anti-ice system removed, while the pressure switch in the engine anti-ice system will be bypassed per the Production EFIX 73X-1802-0011.

Status

For airplanes prior to Line Number 7000, a retrofit plan was approved and added to PRR 3M0133 with the three following service bulletins (SB) included:

1. SB 737-30-1074 EAI Operating Pressure Switch Removal

2. SB 737-30-1075 WAI Indication Pressure Switch Removal

3. SB 737-30-1076 WAI and EAI ADIRU High Altitude Signals Cap and Stow

Interim Action

N/A

Final Action

Creation of Production EFIX 73X-1802-0011 to bypass the pressure switches to resolve the engine anti-ice COWL VALVE light and wing anti-ice L/R VALVE light anomalies on airplanes starting from Line Number 7000.

Removal of the indication pressure switches from the wing anti-ice system on airplanes starting from Line Number 7138 and on; and additionally remove the operating pressure switches from the engine anti-ice system on airplane Line Numbers 6798, 7260, 7273, 7285, 7318, 7326, 7333, 7335, 7351, 7355, 7361 through 7366, 7370 through 7397, 7399 through 7405, 7408, 7411, 7414 through 7434, 7436 through 7461, 7464 and on.

For airplanes prior to Line Number 7000, Boeing has released the three service bulletins referenced in the Status section of this FTD article.

Milestones

Change Committed: 13-MAR-2018 (complete)

Production Incorporation:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

EFIX 73X-1802-0011 Line Number 7000: Jun-2018 (completed)

PRR 3M0133 WAI Only Line Number 7138: Sep-2018 (completed)

PRR 3M0133 EAI and WAI Line Number 6798, 7260, 7273, 7285, 7318, 7326, 7333, 7335, 7351, 7355, 7361 through 7366, 7370 through 7397, 7399 through 7405, 7408, 7411, 7414 through 7434, 7436 through 7461, 7464 and on: Apr-2019 (completed)

Service Bulletin Availability:

SB 737-30-1076 WAI and EAI ADIRU High Altitude Signals Cap and Stow: May-2019 (completed)

SB 737-30-1075 WAI Indication Pressure Switch Removal: May-2019 (completed)

SB 737-30-1074 EAI Operating Pressure Switch Removal: Mar-2021 (completed)

Operator Action

The engine anti-ice COWL VALVE light and wing anti-ice L/R VALVE light anomalies are considered to be nuisance conditions since the system recovers in 10 to 20 seconds. Boeing recommends impacted operators to perform the referenced service bulletins to mitigate nuisance indications. Until the three service bulletins (SB) are incorporated, the below guidance can be followed to resolve the nuisance COWL VALVE and L/R VALVE light conditions.

If the COWL VALVE light(s) illuminate with the MASTER CAUTION and the amber ANTI-ICE light on the system annunciator panel at altitude FL230 and below, wait 20 seconds after illumination of the MASTER CAUTION. If the COWL VALVE light(s) extinguish, continue normal operations. No further crew action is needed. No maintenance logbook write up is needed.

If the L VALVE or R VALVE light(s) illuminate with the MASTER CAUTION and the amber ANTI-ICE light on the system annunciator panel at altitude above FL230, wait 20 seconds after illumination of the MASTER CAUTION. If both the L VALVE and R VALVE lights extinguish, continue normal operations. No further crew action is needed. No maintenance logbook write up is needed.

Boeing recommends that operators review the referenced Flight Crew Operations Manual Bulletins (FCOMBs) and become familiar with the particulars of the nuisance illumination of the engine anti-ice COWL VALVE light(s) and wing anti-ice L/R VALVE light(s).

Part Information

Not applicable.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Affected Documents

Flight Crew Operations Manual Bulletin (FCOMB) tbc-12 rev: 1, dated 04-APR-2018

Flight Crew Operations Manual Bulletin (FCOMB) tbc-13 rev: 1, dated 04-APR-2018

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-30-1074		03/31/2021
Service Bulletin (SB)	737-30-1075		05/07/2019
Service Bulletin (SB)	737-30-1076		10/28/2019
Production Revision Record (PRR)	3M0133		
Other	Production EFIX 73X-1802-0011		
Flight Crew Operations Manual Bulletin (FCOMB)	tbc-13	1	04/04/2018
Flight Crew Operations Manual Bulletin (FCOMB)	tbc-12	1	04/04/2018

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991