FLEET TEAM DIGEST

737MAX-FTD-30-21001

Issue Title : 737 MAX Dual Un-Annunciated Loss of Engine Anti-Ice (EAI) Due to Single Non-Normal Event

Airplane Model	ATA	Minor Model(s)
737MAX	3021-00	-8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
07/30/2021	11/23/2022	11/21/2022
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated the Status, Final Action, and Milestones sections for closure.

All action items are completed and this FTD artilce is closed.

All changes are highlighted in blue text.

Description

The Engine Anti-Ice (EAI) system input power architecture has a potential single point of failure internal to the Standby Power Control Unit (SPCU), which can result in a non-latent loss of the entire battery bus. This will result in loss of all power sources to the EAI 1 and 2 control and indication, which is un-annunciated to the flight crew. Un-annunciated loss of both EAI systems is potentially catastrophic in icing conditions, and can result in loss of Continued Safe Flight and Landing (CSF&L).

Background

In the development of the MAX, the EAI input power architecture was changed from the NG design, which made the MAX EAI system susceptible to this single point failure in the SPCU. As such, this issue is not applicable to the NG.

Although the EAI input power architecture differs between the NG and MAX, the battery bus design of the SPCU is common to both. Boeing notes that there have been no known occurrences of this failure mode of the SPCU in over 218 million flight hours on the NG and MAX fleets.

Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing has identified the design solution, which includes a wiring change at the aft end of the P5 overhead panel that will allow each 28VDC bus to supply power to the same side EAI system in the event of a failure of the respective battery bus. Excerpts of the functional schematic illustrating the fix are provided in the Attachments section.

The solution will be incorporated in production for all -7, -8200, and -10 airplanes. Production incorporation for -8 and -9 airplanes was completed in March 2022.

For -8 and -9 airplanes that did not incorporate the solution in production, Boeing issued Alert Service Bulletin (SB) 737-30A1083 on 18-Nov-2022 to inform operators how to restore compliance.

Boeing's compliance recommendation is to complete Alert SB 737-30A1083 within three (3) years from the original issue date. Boeing submitted its compliance recommendation to the FAA on 17-Jun-2021, and received FAA approval for this recommendation on 14-Jul-2021.

Interim Action

There is no interim action.

Final Action

Boeing incorporated the design solution in production and issued 737 MAX Alert Service Bulletin (SB) 737-30A1083 to inform operators on how to restore compliance.

Boeing notes that SB 737-30-1076 also includes wiring changes at the P5 panel. If SB 737-30-1076 has not yet been incorporated, operators may want to accomplish it at the same time as Alert SB 737-30A1083. For more information on SB 737-30-1076, please see Fleet Team Digest (FTD) article 737MAX-FTD-30-18001.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Safety Decision: 26-Apr-2021 (complete)

Root Cause Established: 20-May-2021 (complete)

Solution Selected: 20-May-2021 (complete)

Compliance Recommendation submitted to FAA: 17-Jun-2021 (complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Lead Airline Call (LAC): 07-Jul-2021 (complete)

FAA Approval of Compliance Recommendation: 14-Jul-2021 (complete)

Change Committed for -7/-8200/-10: May 2021 (complete)

Change Committed for -8/-9: March 2022 (complete)

Production Incorporation: L/N 6744 (-7), L/N 7285 (-8200), L/N 7644 (-10), L/N 8210 (-8/-9)

Service Bulletin Available: 18-Nov-2022 (complete)

Parts Available: 18-Nov-2022 (complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Related Problem (SRP)	737MAX-SRP-30-0061		
Service Bulletin (SB)	737-30A1083		11/18/2022
Service Bulletin (SB)	737-30-1076		
Fleet Team Digest Article (FTD)	737MAX-FTD-30-18001		

Related Categories

- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

Attachments:

a) EAI Schematic

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991