FLEET TEAM DIGEST

737MAX-FTD-30-22001

Issue Title : 737 MAX Wing Anti-Ice (WAI) L/R VALVE Light Illumination - Valve Position Disagreement Faults

Airplane Model	ATA	Minor Model(s)
737MAX	3011-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
05/09/2022	10/13/2026	06/27/2025
Estimated Completion Date	**Next Update Date**	
08/15/2028	01/29/2027	

Revision Description

Updated Status and Milestones sections to reflect current project status.

Applicability

All 737 MAX airplanes.

Description

737 MAX operators are reporting early removals of Wing Anti-Ice Valve (WAIV) Part Numbers (P/N) 63216068-2 and 63216068-3 due to Wing Anti-Ice (WAI) L/R VALVE light illuminations, which indicates a disagreement between the valve position and switch selection on the P5-11 panel.

When the WAI switch is selected OFF, the L/R VALVE light will stay illuminated if the valve is failed open.

When the WAI switch is selected ON, the L/R VALVE light will stay illuminated if the valve is failed closed.

Background

There are multiple 737 MAX operators that have reported schedule interruptions due to the illumination of the L/R VALVE lights during cold weather operations. The majority of the schedule interruption events were attributed to WAIV failing to open when the WAI switch is selected ON.

Most of the faults cannot be duplicated on the ground and the WAIVs had been confirmed to be No Fault Found (NFF) at the shop.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Status

Potential causes for WAI L/R VALVE light illuminations include the following:

1. Left WAIV Sense Line Freezing

Boeing has received data from an operator confirming that moisture freezing in the valve's inlet sense line is resulting in the left WAIV failing to open when WAI is selected ON. The left side WAIV installation is more vulnerable to internal sense line freezing due to its orientation. On the left side, the valve's inlet sense line is at the bottom, while on the right side of the installation, it is located at the top.

Boeing updated the Interactive Fault Isolation Manual (IFIM) Task 30-11-00-810-808 and created Aircraft Maintenance Manual (AMM) Task 30-11-11-200-801 to remove the sense line and dry it out while the WAIV remains on the wing.

2. Electrical/Wiring Issue

When WAI is selected OFF, the WAI L/R VALVE light can illuminate due to a loss of ground at the valve's closed position switch.

3. Nuisance Indication

During descent, when WAI is used at altitudes above FL230, nuisance illumination of WAI L/R VALVE light can occur on airplanes with Wing Thermal Anti-Ice (WTAI) pressure switches. This issue is discussed in Fleet Team Digest (FTD) article 737MAX-FTD-30-18001. The production solution for this issue is provided in Boeing Service Bulletins (SB) 737-30-1075 and 737-30-1076.

4. Lanyard Assembly Binding Manual Locking Mechanism

Due to the length of the lanyard assembly, it has the potential for binding with the manual locking mechanism causing the valve to be stuck partially open and not operational. Honeywell SB 63216068-30-0001 shortens the lanyard from 5.25 inch (133.4 mm) to 2.85 inch (72.4 mm) to eliminate the risk of the lanyard binding the manual lock.

5. Right WAIV Solenoid Freezing

Boeing and Honeywell investigated Right WAIV removals and found water accumulation at the solenoid inlet area. Water freezing at the solenoid in-flight would cause the valve to fail to open.

Boeing and Honeywell investigated a dry-out procedure using a ground cart. The dry-out procedure is intended to vaporize the moisture and vent it out of the honest orifice. However, when validating the proposed dry-out procedure, we found that it would not work on WAIV P/N 63216068-3 because there is no honest orifice. Please note that the schematic in Component Maintenance Manual (CMM) 30-10-32 shows an honest orifice for both P/Ns 63216068-2 and 63216068-3. P/N 63216068-2 has an honest orifice, while P/N 63216068-3 does not. At this time, about half the WAIV population are -2 valves. Since it could be difficult to identify the WAIV P/N when the valve is installed, we are no longer pursuing the dry-out procedure for the fleet.

Boeing and Honeywell conducted a Technical Coordination Meeting (TCM) in September 2023 and decided to further evaluate the increase in port leakage to address the left WAIV sense line freezing and right WAIV solenoid freezing issues.

Boeing completed our review of the increased port leakage design proposal and decided not to pursue this solution due to unfavorable fuel penalties.

Boeing and Honeywell are currently working on a design that utilizes a sense line weep hole, which will allow water to drain from the sense line of the Left WAIV installation location and address the majority of valve failures due to freezing. While working through the design process, the team discovered a thermal limitation for the blowout door seal located below the WAIV. The temperature of the blowout door seal (BMS5-45) cannot exceed 200 degrees F. Thermal analysis models show that the current proposed weep hole design would result in the blowout door exceeding 200 degrees F. Due to this discovery, the proposed weep hole design is being reassesed by Boeing and Honeywell. Status will be provided in an upcoming Fleet Team Call based on completion of the ongoing Honeywell Feasibility study.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

Left WAIV

Utilize IFIM Task 30-11-00-810-808 and AMM Task 30-11-11-200-801 to remove water from the sense line while the valve is on-wing. Please note that a Temporary Revision (TR) was released for AMM Task 30-11-11-200-801 in order to provide further clarity per the below notes when cycling the WAIV per the AMM task:

- The WAIV sense line needs to be warm 40 degrees F (best time to perform task is immediately after last flight of the day when the WAIV chamber is still warm)
- The WAIV inlet pressure needs to be high (isolation valve closed with the duct pressure being at least 30 PSIG or more)
  - If WAIV inlet pressure is too low (isolation valve open), water can be trapped within solenoid

Final Action

Incorporate new WAIV design to production and release component service bulletin.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

- Investigation Initiated: April-2022
- Left WAIV IFIM/AMM Update: January-2023 (complete)
- Root Cause Established: January-2023 (complete)
- Project Plan/Schedule: February-2024 (complete)
- Complete Design and Analysis for Increased Port Leakage Design: August-2024 (complete)
- Complete Initial Evaluation of Weep Hole Solution: 30-March-2025 (complete)
- Complete Functional Testing of Sense Line Weep Hole Design: 23-June-2025 (complete)
- Start of Certification Process: 9-September-2025 (complete)
- Finalize Weep Hole Size: 17-October-2025 (complete)
- Critical Design Review: 6-November-2025 (complete)
- Lower Blowout Door Seal / Gasket Discovery: 12-March-2026 (complete)
- Non-Advocate Review (NAR): 22-April-2026 (complete)
- TR of AMM Task 30-11-11-200-801: 30-September-2026 (complete)
- Honeywell Feasibility Study: 30-October-2026 (target)
- Complete Weep Hole Design Reassessment: to be determined based on above

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-30-1075		05/07/2019
Fleet Team Digest Article (FTD)	737MAX-FTD-30-18001		
Service Bulletin (SB)	737-30-1076		10/28/2019
Service Bulletin (SB)	Honeywell SB 63216068-30-0001		02/16/2021

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Wing Anti-Ice Valve		Honeywell	63216068-2
Wing Anti-Ice Valve		Honeywell	63216068-3

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

Attachments:

a) May 2026 737 FTM Presentation - WTAIV Issues

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991