# FLEET TEAM DIGEST

## 737MAX-FTD-30-24001

**Issue Title :** Window Heat Faults - PCB Assy INOP Condition

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3041-11 | -8, -8200, -9, -BBJ |

| Other Model(s) | ECCN |
|---|---|
| 737NG | 9E991 |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 04/04/2024 | 07/29/2026 | 06/30/2026 |

| Estimated Completion Date | Next Update Date |
|---|---|
| 12/31/2027 | 10/30/2026 |

## Revision Description

Provide updates for the status and milestones for this project.

## Description

The Window Heat Control Unit (WHCU), P/N 83000-27904, is reporting window OVRHT light illumination condition resulting in operational delays and unscheduled removals. The WHCU provides window heat, temperature monitoring, system status, and fault indication.

Shop findings of operator-returned units identified an issue with the Printed Circuit Board (PCB) inside the WHCU, where the WHCU would fail upon power start-up sequence (PCB Assy INOP fault). Further analysis identified the failed sub-component as the A2 PCB Assy TRIAC (Triode for AC). The TRIAC is a semiconductor device that is commonly used in power regulation and switching applications.

Note, the PCB Assy INOP fault condition described in this FTD is not related to the MOD A WHCU incorporation as the PCB Assy INOP fault condition is observable on both pre and post MOD A WHCUs. Refer to Fleet Team Digest (FTD) 737MAX-FTD-30-20001 for more information regarding the MOD A update.

## Status

Boeing and the WHCU Supplier, Koito, are investigating the PCB Assy INOP fault condition. Testing of various operator returned units determined the cause to be due to WHCU PCB Assy TRIAC failures. The failure was unable to be replicated in a lab environment, but it is likely due to noise on the power bus when multiple TRIACs are being turned on at the same time. This leads to the TRIACs failing due to the resulting over current.

Koito's initial proposal, communicated in previous FTD updates, would have resulted in more reliable TRIAC switching. However, that change was rejected due to a failure to meet airplane power system requirements.

In order to comply with airplane power system requirements and offer an improvement to the WHCU performance, Koito has released a minor change to improve the reliability of the A2 PCB Assy while a longer term solution is investigated. This minor change is projected to increase reliability by 20% and will be implemented in-service via attrition. Any repairs done after 15 Oct 2025 by Aviation Technical Services (ATS) regarding the A2 PCB Assy have the updated change.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Boeing will continue to monitor the fleet and work with Koito on a longer term solution to improve the WHCU reliability.

The next steps Boeing and Koito are currently taking to develop further improvements include:

- Completing a detailed review and analysis to confirm the corrective action.
- A timeline and implementation plan will be published as soon as the analysis is finalized.

Koito Engineering has submitted the Proposed Design Change to Boeing in July 2026 for Boeing review.

## Interim Action

Boeing recommends operators continue to follow the iFIM to perform a system reset as required if a window OVRHT light illuminates (IFIM 30-41-00-810-828, -829, -830, and -831). If the OVRHT light is no longer active after the system reset, then the WHCU does not need to be replaced.

Boeing recommends operators to send any failed/removed WHCUs to the WHCU Supplier's repair center, Aviation Technical Services (ATS) for evaluation.

## Final Action

Pending Investigation

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Completed
Production Improvement: Implemented at Serial Number – S/N 8951

Koito Proposed Design Change Submission to Boeing: July 2026

Preliminary Design Review (PDR) (ECD) 4Q2026

Critical Design Review (CDR) (ECD) 2Q2027

Final Solution: Design Change (ECD) TBD

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Fault Isolation Manual (FIM) | FIM 30-41-00-810-828, -829, -830, and -831 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-30-20001 | | |

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Parts List

| Part Name | Boeing Part Number | Supplier Name | Supplier Number |
|---|---|---|---|
| Window Heat Control Unit (WHCU) | 10-61833-9 | Koito | 83000-27904 |

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

## Attachments:

a) Fleet Team Meeting Presentation May 2026

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991