FLEET TEAM DIGEST

737MAX-FTD-30-25001

Issue Title : Windshield Wiper Blade and Arm Nut Torque Range Change

Airplane Model	ATA	Minor Model(s)
737MAX	3042-00	-8, -8200, -9, -BBJ

Other Model(s)	ECCN
737, 737NG	9E991

Originated Date	Last Revised Date	Created On
06/11/2025	10/27/2025	10/02/2025

Estimated Completion Date	Next Update Date

Revision Description

AMM Task 30-42-11-400-801 has been revised to reflect the correct torque values for installing the wiper blade assembly onto the wiper arm assembly. Therefore this FTD article is considered closed.

Description

This Fleet Team Digest (FTD) article notifies operators of a revision to the 737-8/-8200/-9/-BBJ Aircraft Maintenance Manuals (AMMs) in regards to the range of torque values applied to the nut used for fastening the windshield wiper blade onto the windshield wiper arm.

Background

Boeing revised the windshield wiper installation/rigging drawings to increase the torque value applied to the nut used to fasten the windshield wiper blade onto the windshield wiper arm. The previously listed range of torque values was between 14 and 18 in-lbs and has been revised to a range of values between 18 and 20 in-lbs. This change in torque values will help minimize the possibility of slippage and unstable rotation of the wiper blade, which will minimize the possibility of subsequent damage to the windshield, aircraft skin, and/or structures surrounding the windshield.

Due to the aforementioned change in Boeing documentation, the 737-8/-8200/-9/-BBJ Aircraft Maintenance Manuals (AMMs) will also need to be revised to match the torque values listed within the drawings. The torque values will be revised from a range of values between 14 and 18 in-lbs to a range of values between 18 and 20 in-lbs.

Status

Boeing had submitted a Publication Change Request (PCR) that initiated the revision of AMM Task 30-42-11-400-801 to list the 18 to 20 in-lb torque range. AMM Task 30-42-11-400-801 has been revised to reflect the change in torque values.

Interim Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

None

Final Action

Boeing has revised the applicable AMM Task to list the 18 to 20 in-lb torque range.

The applicable AMM Task for 737-8/-8200/-9/-BBJ aircraft is AMM Task 30-42-11-400-801.

Milestones

Revision of AMM Task 30-42-11-400-801: 15-SEP-2025 (complete)

Operator Action

Operators may inspect the torque values of the nut that connects the wiper blade to the wiper arm and adjust the torque (as needed) to a value between 18 and 20 in-lbs. Boeing does not have a recommended time frame for when the inspection and new torque range value should be applied and suggests performing these actions at a convenient maintenance opportunity.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Aircraft Maintenance Manual (AMM)	30-42-11-400-801		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Windshield Wiper Blade Assembly	2315M20-3		
Windshield Wiper Blade Nut	MS21044N08		
Windshield Wiper Arm Assembly	2314M72-1		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991