FLEET TEAM DIGEST

737MAX-FTD-30-25002

Issue Title : Non-Compliant Windshield Wiper Motor/Converter Part Numbers 2313M-347-5 and 2313M-348-5

Airplane Model	ATA	Minor Model(s)
737MAX	3042-21	-10, -7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
737, 737NG	9E991	

Originated Date	Last Revised Date	Created On
09/16/2025	10/07/2026	09/21/2026
Estimated Completion Date	**Next Update Date**	
12/23/2026	12/23/2026	

Revision Description

Revising article with updated certification schedule due to ongoing qualification testing.

Description

This Fleet Team Digest (FTD) article provides operators with information regarding the obsolescence of the Part Number (P/N) 2313M-347-4 (Left-Hand) and P/N 2313M-348-4 (Right-Hand) Windshield Wiper Motor Converters (WMC)s (commonly referred to as the -4 WMCs), the introduction and non-compliance of the P/N 2313M-347-5 (Left-Hand) and P/N 2313-348-5 (Right-Hand) WMCs (commonly referred to as the -5 WMCs), and the design efforts towards the P/N 2313M-347-6 (Left-Hand) and P/N 2313-348-6 (Right-Hand) WMCs (commonly referred to as the -6 WMCs).

Background

The -4 WMCs have high failure rates in the fleet, resulting in service interruptions. According to shop reports from the supplier of the WMCs (Collins Aerospace), the primary drivers for the failed units included reliability issues with the International Rectifier (IR) module and internal issues with the A3 Circuit Card Assembly (CCA) that caused power supply failures. Additionally, some of the electronic components internal to the -4 WMCs were identified to become obsolete: the IR module and the Programmable Logic Device (PLD) CCA. The reliability issues in conjunction with the obsolete components within the -4 WMCs led to the development of the -5 WMCs as replacement parts. The -5 WMCs include a re-designed Power CCA, a re-designed PLD CCA, and a re-designed Electromagnetic Interference (EMI) Filter CCA. The cut-in aircraft Line Number (L/N) to be delivered with the -5 WMCs was L/N 9187 through Production Revision Record (PRR) 3M0187.

After certification activities and the PSOC (Project Statement of Completion) were completed for the certification project phases that include the 737-8/-9/FAA-8200 fleet, Boeing discovered issues with the new -5 WMCs where the wiper motors were not functioning as intended when installed on the aircraft. The wipers were sweeping past the lower edge of the windshield and exhibiting inconsistent behavior during the sweeps (hesitation during full travel) and parking operations (inconsistent parking spots). Specifically, the wipers are not intended to sweep past the lower edge of the windshield and are intended to park out of the line of sight of pilots in a designated area at the bottom of the windshield. These issues led to a delivery hold and the initiation of a Potential Notice of Non-Compliance (pNNC), which led to Notice of Non-Compliance (NNC) N25-32.

Boeing worked with the Collins Aerospace Engineering Team to test the -5 WMCs on a full scale 737 fuselage to collect data to validate hypotheses for root causes of the observed behavior. After sufficient test rig and flight testing, collaboration with Boeing technical pilots and Airline Safety Engineering, and review of the Root Cause Corrective Action (RCCA) provided by Collins

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Aerospace, it was determined that aircraft equipped with the -5 WMCs were in a condition for safe operation. While the behavior of the -5 WMCs is undesirable, these behaviors do not impede the flight crew's field of view and are not deemed to be a potential safety concern. Following the airplane safety determination, Boeing lifted the delivery hold for certified 737-8, 737-9, and non-EASA 737-8200 minor models. While the certification process covered all 737 MAX and NG aircraft, the timing of when the non-compliance was found made it so the certification of the -5 WMCs was only accomplished for 737-8, 737-9, and non-EASA 737-8200 aircraft. Subsequently, Boeing sent a letter to the FAA along with applicable 8100 forms to address the EASA 737-8200 minor model that did not receive -5 certification. Through a FAA-EASA bi-lateral agreement, the applicable compliance deliverables for certifying the -5 for FAA 737-8200 aircraft also applied to EASA 737-8200 aircraft.

Due to the non-compliance discovered on the -5 WMCs, Boeing and Collins Aerospace began working on the development and certification of the new -6 WMCs to resolve the compliance issue and be used on all 737CL/NG/MAX aircraft.

Status

Boeing created PRR 3M0392 to initiate the design and certification of the -6 WMCs. -6 WMC integration testing was completed on 14-August-2025.

The 737 MAX Illustrated Parts Catalog (IPC) was revised to include a two-way interchangeable note, where -5 WMCs can only be installed on 737-8, 737-9, and 737-8200 aircraft. EASA considers the use of the -5 WMCs on EASA certified 737-8200 aircraft as validated through a FAA-EASA bi-lateral agreement.

Interim Action

Collins Aerospace has assessed -4 WMC repair capability for the obsolete components and has noted there is a third-party vendor with Designated Engineering Representative (DER) approval that has repair capability for the -4 WMCs. This repair capability may be facilitated by contacting Intertrade at collinsintertraderepairs@collins.com.

Due to the low global supply of -4 WMCs, the inventory of -4 WMCs are under AOG management control. If -4 WMCs are needed on a critical/AOG basis, impacted operators may submit an AOG order directly to Collins Aerospace using the following contact information:

AOG/Emergency Services (24 hours per day; 7 days per week)

Phone: +1 319-295-5000 Option 1, Option 1

Email: avionicssupport@collins.com

Operators can also send a BCS message to Boeing regarding the Collins AOG order information, including the purchase order (PO), Part Number (P/N), and quantity (QTY) for each component.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

The -6 WMCs will be certified and made widely available to operators.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

- Non-Compliance Identified: 27-March-2025 (completed)
- Safety Determination: 16-April-2025 (completed)
- Modified -5 WMC Testing: 21-May-2025 (completed)
- May 2025 Fleet Team Call: 29-May-2025 (completed)
- July 2025 Fleet Team Call: 17-July-2025 (completed)
- 737 MAX IPC Revision: 5-August-2025 (completed)
- Collins Aerospace SB Release: 11-August-2025 (completed)
- August 2025 Fleet Team Call: 14-August-2025 (completed)
- -6 WMC Integration Testing: 14-August-2025 (completed)
- November 2025 Fleet Team Call: 13-November-2025 (completed)
- February 2026 Fleet Team Call: 12-February-2026 (completed)
- -6 WMC Qualification Testing Start: May-2026 (completed)
- -6 Certification: December-2026 (target)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Other	737 Wiper Motor FTC Presentation - August 2025		
Illustrated Parts Catalog (IPC)	30-42-21-01		
Other	737 Wiper Motor OOS Charts 29-MAY-2025		
Other	737NGMAX 2025 Wiper Motors FTC Presentation - JULY		
Production Revision Record (PRR)	3M0392		
Production Revision Record (PRR)	3M0187		
Other	737 Wiper Motor Fleet Team Call - November 2025		
Other	737 Wiper Motors Fleet Team Call - February 2026		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Windshield Wiper Motor Converter	10-61329-44	Collins Aerospace	2313M-348-5
Windshield Wiper Motor Converter	10-61329-45	Collins Aerospace	2313M-347-6

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Windshield Wiper Motor Converter	10-61329-46	Collins Aerospace	2313M-348-6
Windshield Wiper Motor Converter	10-61329-41	Collins Aerospace	2313M-347-4
Windshield Wiper Motor Converter	10-61329-42	Collins Aerospace	2313M-348-4
Windshield Wiper Motor Converter	10-61329-43	Collins Aerospace	2313M-347-5

Related Categories

- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board
- Obsolescence : Information on parts that are obsolete, becoming obsolete, or have excessive lead times

Attachments:

a) May 2026 737 FTM Presentation - Wiper Motors

b) 737NGMAX 2025 Wiper Motors FTC Presentation - JULY

c) 737 Wiper Motor Fleet Team Call - August 2025

d) 737 Wiper Motor OOS Charts 29-MAY-2025

e) 737 Wiper Motor Fleet Team Call - November 2025

f) 737 Wiper Motors Fleet Team Call - February 2026

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991