FLEET TEAM DIGEST

737MAX-FTD-31-17003

Issue Title : Incorrect Date on CFAST card

Airplane Model	ATA	Minor Model(s)
737MAX	3131-22	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
06/02/2017	02/08/2024	01/30/2024

Estimated Completion Date	Next Update Date

Revision Description

Revised references, status, final action and milestones sections announcing the release of Digital Flight Data Acquisition Unit (DFDAU) Airplane Condition and Monitoring System (ACMS) BlockPoint (BP) 1.4 Operational Software (OPS) Upgrade. Recommend FTD closure.

Applicability

737 MAX Airplanes with Teledyne Digital Flight Data Acquisition Unit (DFDAU) Part Number (P/N) 2245000-101 and Compact Fast (CFast) card.

Description

The CFast card is an optional memory card used to store and collect data when installed in the DFDAU. More information on CFast Media Recommendations and Best Practices can be found in Teledyne Service Letter SL2245000 NO. 1.

The date and timestamp on some of the CFast card files have been observed to be incorrect. CFast card data is not affected and the correct dates are recorded in the flight data. Airplane data recording in the CFast card is not interrupted and there is no loss of function to the CFast card.

No crew action is required and the airplane is fully operational.

Status

The root cause of the nuisance condition has been determined to be the file system not correctly implementing the flag MNT_NOATIME, so access times can be set to random values.

The operating system for DFDAU is INTEGRITY from Green Hills Software. When Airplane Condition and Monitoring System (ACMS) accesses the CFast card, it uses the INTEGRITY standard file system. When mounting the card to the file system, it uses the flag MNT_NOATIME to request no automatic update of the file access times.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

DFDAU ACMS OPS BlockPoint 1.4 has been released and had corrected this issue. Boeing released Service Bulletin 737-31-2130, December 07 2023 and Service Letter 737-SL-31-086, dated December 08 2023.

Interim Action

None

Final Action

The Cfast card date and timestamp have been corrected with the latest BlockPoint 1.4 OPS update.

Boeing released Service Bulletin 737-31-2130, and Service Letter 737-SL-31-086. The Service Bulletin incorporates BlockPoint 1.4 software update part number TDY4E-7095-1805.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 31-MAY-17 (complete)

Solution Selected: September 17, 2022 (complete)

Change Committed: January 2024 (complete)

Production Incorporation: Line Number 8920 (complete)

Service Bulletin Available: SB-737-31-2130, dated 07 December 2023 (complete)

Service Letter: 737-SL-31-086, dated 08 December 2023 (complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Information Letter (SIL)	Teledyne Service Letter SL2245000 NO. 1.		
Service Bulletin (SB)	737-31-2130		12/07/2023
Service Letter (SL)	737-SL-31-086		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
DFDAU	2245000-101	2245000-101	Teledyne

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- Technical Focus Item : null

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991