FLEET TEAM DIGEST

737MAX-FTD-31-17004

Issue Title : Incorrect Elapsed Times in Start Reports

Airplane Model	ATA	Minor Model(s)
737MAX	3131-22	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
11/28/2017	02/08/2019	02/08/2019

Estimated Completion Date	Next Update Date

Revision Description

The 737MAX DFDAU ACMS Baseline Software BCG39-L200-0001 was installed in production starting in Line Position 7258.

The Boeing Service Letter 737-SL-31-068 was released on January 31, 2019.

Applicability

737 MAX Airplanes below Line Number 7258 with Teledyne Digital Flight Data Acquisition Unit (DFDAU) Part Number (P/N) 2245000-101.

Description

Analysis of the Airplane Condition and Monitoring System (ACMS) Start Report and Engine Full Flight Data (FFD) from in-service airplanes shows significant discrepancies in the data captured in the ACMS Start Report:

-The elapsed time counters show a significant and seemingly random variation from what the time-series data would indicate

-The data that is captured appears to be done at close to a 2.5 second delay from the time that the data recording trigger becomes TRUE (Note: ACMS Specification requires that this data recording trigger bit stay TRUE for a minimum of 2.5 seconds)

Operators should not attempt to use the elapsed times in the Start Reports for any purposes. The values recorded do not represent what the Service Reported Discrepancy (SRD) defines. These discrepancies make the data unusable for trending the engine start sequence. The airplane is fully operational.

Status

Corrective action is the updated DFDAU ACMS Baseline software to fix how elapsed time is handled.

The DFDAU ACMS Baseline Database also includes the following updates and fixes:

1) Modifications of the data captured conditions in the Climb B31, Stable Cruise B43, and Takeoff B44 Reports.

2) Time period in history for data captured modified from 4 seconds to 5 seconds in the Climb B31, Engine Start Left B39, Engine Start Right B40, Stable Cruise B43, and Takeoff B44 Reports.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The 737MAX DFDAU ACMS Baseline Software BCG39-L200-0001 was installed in production starting in Line Position 7258.
The Service Letter 737-SL-31-068 737MAX DFDAU ACMS Software Update with instructions to retrofit BCG39-L200-0001 was released on January 31, 2019.

Interim Action

None.

Final Action

The DFDAU ACMS Baseline Software BCG39-L200-0001 was installed in production starting in Line Position 7258.
The Service Letter 737-SL-31-068 737MAX DFDAU ACMS Software Update with instructions to retrofit BCG39-L200-0001 was released on January 31, 2019.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 28-AUG-17 (complete)

Solution Selected: 15-JAN-18 (complete)

Change Committed: 22-JAN-18 (complete)

Production Incorporation: Line Number 7258 (complete)

Service Letter 737-SL-31-068 Available: 31-JAN-19 (complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	737-SL-31-068		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
SFE DFDAU	2245000-101	Teledyne	2245000-101

Related Categories

- In Service Occurrences : null

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991