FLEET TEAM DIGEST

737MAX-FTD-31-18001

Issue Title : Nuisance DPC-1 Status Message and DPC-1 INCOMPLETE BITE Maintenance Message

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
01/19/2018	10/19/2018	10/12/2018
Estimated Completion Date	**Next Update Date**	

Revision Description

Closed FTD article with Final Action to incorporate vendor Service Bulletin.

Description

The Display Processing Computer (DPC) runs a power up BITE sequence when it is turned on. This BITE sequence takes about 30 seconds to complete. During this process it requires both the primary and backup power to be connected in order to complete the test. If the process does not complete, maintenance message 31-02921 'DPC-1 INCOMPLETE BITE' may log, which would cause a 'DPC-1' status message.

Boeing has determined this can also happen when the airplane is not connected to external power and an APU start is initiated from battery prior to the DPC completely coming online to drive the displays. The APU start can draw down the battery voltage enough for the DPC to sense that it has 'lost' one of its sources of power during its power up BITE sequence. This power-on scenario would cause the noted nuisance faults. Note: the faults are not set if the airplane is powered up from external power.

Boeing and Rockwell Collins believe this is a nuisance issue. The DPCs are still operational and as long as the faults clear, the DPCs do not need to be removed.

Status

Boeing received reports from multiple operators seeing a 'DPC-1' status message and correlated maintenance message 31-02921 'DPC-1 INCOMPLETE BITE' occasionally during airplane power-on. Boeing began to conduct a root cause investigation with supplier Rockwell Collins.

Boeing analyzed different sets of data associated with this nuisance issue. The DPC-1 INCOMPLETE BITE message is latched at airplane power up if the condition exists. The fault logs in the Onboard Maintenance Function (OMF) are stored in the Network File Server (NFS). The NFS takes 7 minutes to completely power on and therefore the fault may log anywhere from the Engine Start to the Taxi Out phase.

Boeing conducted airplane testing to attempt to reproduce the effect. Boeing was able to reproduce the issue and identified root cause.

Rockwell Collins incorporated this fix into their production line.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The DPC serial number cut in for the resistor change is 4F8TLY.

Rockwell Collins released a Service Bulletin Solution DPC-2120-31-1 for this issue as of August 2018.

Boeing began to implement the DPCs with the resistor change into airplane production during the last week of September 2018.

Note: The cut in takes place over multiple line numbers.

Therefore there is not a specific line number where the upgraded DPCs were incorporated.

Interim Action

In order to avoid experiencing these nuisance faults Boeing suggests to allow the DPC to complete its power on process and drive the displays prior to performing an APU start. This takes approximately 30 seconds once the battery is turned on.

If the issue is seen, Boeing recommends to follow the IFIM procedures as documented.

Final Action

Boeing advises operators to incorporate the Rockwell Collins SB DPC-2120-31-1 for applicable DPCs (Serial Numbers 4F8TMV and below).

Boeing advises operators to incorporate at their earliest convenient maintenance opportunity to prevent this issue from recurrence during the warranty period stated in the SB.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fault Isolation Manual (FIM)	IFIM Task 31-65-00-810-833		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Display Processing Computer (DPC)		Rockwell Collins	822-3252-101

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991