FLEET TEAM DIGEST

737MAX-FTD-31-18002

Issue Title : ACMS Reports Not Generating

Airplane Model	ATA	Minor Model(s)
737MAX	3131-22	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
01/25/2018	02/08/2019	02/05/2019

Estimated Completion Date	Next Update Date

Revision Description

The retrofit Boeing Service Bulletin 737-31-1801 Digital Flight Data Acquisition Unit (DFDAU) BlockPoint 1 (BP1) Software Update was released on November 29, 2018.

The Boeing Service Letter 737-SL-31-070 was released on February 7, 2019.

Applicability

737 MAX Airplanes below Line Number 7258 with Teledyne Digital Flight Data Acquisition Unit (DFDAU) Part Number (P/N) 2245000-101.

Description

Airplane Condition Monitoring System (ACMS) reports are not being generated.

This is a known issue with the Secure Digital (SD) card getting corrupted which causes the box to stop generating reports for one or more partitions. Symptoms may also include loss of ACMS prompt on the Multi-Purpose Control Display Unit (MCDU).

Status

Teledyne investigations have found the failure is caused by the Real Time Operating System (RTOS) journaling file system which is the software interface to the internal SD card. Teledyne can duplicate the failure in the lab and the failure is detectable in the lab.

Corrective action is an update that is implemented in the DFDAU BlockPoint 1 (BP1).
The DFDAU BP1 software update is installed in production starting with Line Position 7258.
The retrofit Boeing Service Bulletin 737-31-1801 was published on November 29, 2018.
The Boeing Service Letter 737-SL-31-070 was released on February 7, 2019.

Interim Action

If any partition no longer or has never generated reports, first ensure that the required reports are enabled for generation as well as auto-downlinking per 737MAX AMM TASK 31-31-22-860-801 if desired.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

If the correct configuration is already enabled, verify if the Boeing-created Airplane Health Management (AHM) software part, BSM27-H200-0001 is installed. If yes, dataload the Teledyne AHM software part, TDY40-7095-3001. This will reset the application software and should remove the problem. If desired, reload the BSM27-H200-0001 software part for continued operation.

If this does not resolve the problem or if BSM27-H200-0001 was not already loaded on the DFDAU, suggested next step is to remove and replace the DFDAU Part Number (P/N) 2245000-101.

If the ACMS prompt is no longer visible, follow the same steps as above starting at verifying which AHM part is installed.

As the nature of the ACMS issue is sporadic, either of the scenarios could occur again even after following the procedures above. If an ACMS issue occurs again, follow the same procedures as above to reset the ACMS software.

Final Action

The DFDAU BP1 software update is installed in production starting with Line Position 7258.

More information on the DFDAU BP1 software update is available on the Boeing Service Letter 737-SL-31-070 released on February 7, 2019.
The retrofit Boeing Service Bulletin 737-31-1801 was published on November 29, 2018.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 29-JUN-17 (complete)

Solution Selected: 18-JAN-18 (complete)

Change Committed: 05-MAR-18 (complete)

Production Incorporation: Line Position 7258 (complete)

Service Bulletin 737-31-1801 Available: 29-NOV-18 (complete)

Parts Available: 29-NOV-18 (complete)

Service Letter 737-SL-31-070 Available: 07-FEB-19 (complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-31-1801		11/29/2018
Service Letter (SL)	737-SL-31-070		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
SFE DFDAU	2245000-101	Teledyne	2245000-101

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- In Service Occurrences : null

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991