FLEET TEAM DIGEST

737MAX-FTD-31-18003

Issue Title : EFIS Control Panel Reliability Improvements

Airplane Model	ATA	Minor Model(s)
737MAX	3165-12	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
08/23/2018	07/27/2022	07/14/2022

Estimated Completion Date	Next Update Date

Revision Description

Updated References, Status, Interim Action, Final Action and Milestones section to reflect current status regarding release of Service Bulletin DCP-2120-31-2 for Issue 3.

This FTD is now closed as the release of Service Bulletin DCP-2120-31-2 addresses Issue 3.

Description

Boeing has received reports from multiple operators for early removals of the EFIS Control Panel (CP) P/N 822-3252-101, also known as the Display Control Panel (DCP). Boeing has documented removals both in production and in service and notified Collins Aerospace. An ongoing investigation is being conducted to improve reliability.

Background

There are three main reasons the EFIS CP has been removed so far.

1. The encoder on the Baro and Mins knob was found to be installed improperly from a sub-tier supplier. This caused the Baro knob to stick and not set completely. After release the barometric altitude would continue to slowly change on the forward display.
2. The encoder on the Baro and Mins knob has been found to be loose and difficult to change.
3. The return spring in the Baro and Mins knob has been found to fail prematurely, approximately 1-2 years into service, due to spring and encoder design.

Status

Issue 1 - Sticking Encoder/Knob

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Boeing notified Collins Aerospace of the suspect condition found in production. Collins Aerospace's investigation revealed that their sub-tier supplier had a non-conforming installation. Collins Aerospace released a Notice of Escape (NOE) to Boeing. Boeing released a MOM to selected operators who were identified to have an EFIS CP that may have the suspect condition laid out in the NOE.

Collins Aerospace identified a fix and released Service Bulletin DCP-2120-31-B to rectify this issue in November 2017.

Collins Aerospace confirmed that no more units with a suspect condition in production were being sent to Boeing as of December 2017.

Issue 2 - Loose Encoder/Knob

Boeing and Collins Aerospace investigated the removed EFIS CPs more in depth and have found that the encoders could become loose over time. Collins Aerospace determined a fix to torque the encoder more and apply a stronger loctite. Boeing approved the proposed fix as of August 2018.

The new and improved encoders are now in production from Collins Aerospace and are being provided to Boeing.

Collins Aerospace released Service Bulletin DCP-2120-31-1 to improve the loose encoders for in-service units February 2019.

Issue 3 - Fractured Spring within Knob

Boeing and Collins Aerospace investigated the removed EFIS CPs and found the springs are fracturing prematurely due to the design of the spring and encoder. Collins Aerospace determined a fix to replace the current springs with a newly designed spring and encoder.

Collins Aerospace Service Bulletin DCP-2120-31-2 is available for modification of the DCP-2120. The modification addresses fractured return spring condition by replacement of both MINS and Baro encoders. Expected benefit is improved reliability.

Collins Aerospace will modify all DCP-2120's free of charge (FOC) with Service Bulletin DCP-2120-31-2 (523-0834164) for units both in and out of warranty. Incorporation of this Service Bulletin can only be accomplished at Collins Aerospace Service Centers.

Interim Action

Operators are advised to be aware of the available and pending Collins Aerospace SBs that will rectify the current reliability issues experienced with the EFIS CP. See Collins Aerospace Service Bulletin DCP-2120-31-B for Issue 1, Service Bulletin DCP-2120-31-1 for Issue 2 and DCP-2120-31-2 for Issue 3.

Operators may consider proactively sending in their spare EFIS CPs to a Collins Aerospace Service Center if their units are identified as potentially suspect.

If operators are unsure if their units may have the suspect conditions, Boeing advises to contact Collins Aerospace to clarify.

If an operator encounters Issue 3 Baro or Mins knob spring failure, remove and replace faulted DCP-2120 unit and send the

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

faulted unit to a Collins Aerospace Service Center for repair. MMEL 31-62-04-01 can be applied to the Minimum (MINS) reference selector if the switch is not needed for approach procedures. The switch must be repaired or replaced within 10 days of the fault being recorded. There is no MMEL dispatch allowed for a faulted Baro selector knob.

Final Action

If an EFIS CP unit exhibits above noted effects of Issue 1 or Issue 2, Boeing advises to review the applicability of Service Bulletin DCP-2120-31-B and Service Bulletin DCP-2120-31-1 and send any affected units to Collins Aerospace as needed for incorporation of the reliability improvement service bulletins to address the potential fault condition.

If an EFIS CP unit exhibits above noted effects of Issue 3, Boeing advises to review the applicability of Service Bulletin DCP-2120-31-2 and send any affected units to Collins Aerospace as needed for incorporation of the reliability improvement service bulletins to address the potential fault condition.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Service Bulletin DCP-2120-31-B (Issue 1) Available: November 2017 (Complete)

Service Bulletin DCP-2120-31-1 (Issue 2) Available: February 2019 (Complete)

Service Bulletin DCP-2120-31-2 (Issue 3) Available: July 2022 (Complete)

Parts Available: July 2022 (Complete)

Production Incorporation: July 2022 (Complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	DCP-2120-31-1		
Service Bulletin (SB)	DCP-2120-31-B		
Service Bulletin (SB)	DCP-2120-31-2		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Display Control Panel			822-3252-101

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- CRC - Component Reliability Collaboration : Collaborative process to eliminate component removals in production and the during the first year of new airplane in service

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991