FLEET TEAM DIGEST

737MAX-FTD-31-18005

Issue Title : Nuisance ATA 71 Auto Event Snapshot

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
09/12/2018	11/26/2025	11/04/2025
Estimated Completion Date	**Next Update Date**	

Revision Description

There is an update to the Milestone timeline for 737MAX-FTD-31-23002. This FTD will be closed. Please refer to 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2.

Applicability

All 737 MAX airplanes.

Description

There are conditions that have been identified where the Display Processing Computer (DPC) will record nuisance Auto Event Snapshots in the Maintenance Data Pages.

These snapshots have been seen in ATA 21 Air Conditioning, 36 Air Supply, and 71 Performance and Engine Propulsion Control System (EPCS).

The Status Messages associated with these Auto-Event Snapshots include the following, but are not limited to:

- PACK CONTROL CHANNEL L(R)
- BLEED CTRL CARD L(R)
- BLEED CTRL CARD L(R) - ENG DATA
- BLEED CTRL CARD BACKUP L(R)
- BLEED CTRL ICING INHIB L(R)
- BLEED CTRL LIGHT OUTPUT L(R)
- ENG 1(2) LOW OIL PRESS INDICATION
- ENG 1(2) OIL FILTER BYPASS INDICATION
- ENG 1(2) THRUST INDICATION

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- ENG 1(2) REVERSER LIMITED LIGHT

Background

During the airplane power down sequence, the DPC is powered by the hot battery bus for up to 10 seconds to write to Non-Volatile Memory (NVM). During this time period, the Proximity Sensor Electronic Unit (PSEU) and Electronic Engine Controls (EECs) can shut off before the DPC. If the engines and PSEU are shut off but the DPC is still on, the DPC will log the ATA 71 Auto-Event Snapshots. Since the event occurs when the engines are powered off, the Auto-Event Snapshot will contain blank engine parameters. The nuisance ATA 71 snapshots will NOT be accompanied by any maintenance messages and flight deck effects.

There are scenarios during power on, engine start and engine-on functional tests where the Integrated Air Systems Controller (IASC) will have some communication faults causing some of the nuisance Auto-Event Snapshots. See reference 737MAX-FTD-36-19001 for more information.

There are a maximum of 5 recordable snapshots per system for both Auto and Manually recorded events. If more than 5 Manual events are recorded, the oldest is removed from NVM to make room for the newest event. However, for Auto-Event Snapshots, once 5 Auto events are recorded, no additional Auto events will get stored until some of the 5 are erased.

Status

Boeing performed airplane testing and confirmed the nuisance ATA 71 snapshots reported by operators. The nuisance condition occurred on almost every shutdown.

Boeing also confirmed that there is no correlated (or associated) flight deck indication or maintenance message log for these nuisance Auto-Event Snapshots in the testing.

Boeing released the reference Maintenance Tip 737 MT 31-019 to advise operators to clear the snapshot at convenient maintenance intervals.

MAX Displays System (MDS) Block Point (BP) 2 (Service Bulletin 737-31-1929) will incorporate a software fix for nuisance ATA 71 Auto Event Snapshots.

During this investigation, it was found that nuisance auto event snapshots occurred in ATA 21 and 36 as well.

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2 and a list Fleet Team Digest (FTD) articles that are also addressed by the MDS BP 2 release.

Interim Action

Boeing advises to follow the directions in the reference Maintenance Tip 737 MT 31-019 and clear the nuisance ATA 71 Auto Event Snapshots at a convenience maintenance interval regularly.

For ATA 21 and 36 Auto-Event snapshots that appear to occur during nuisance or non-flight scenarios, Boeing requests the following:

1. Please advise the frequency of the apparent nuisance snapshots.

2. Please advise the conditions surrounding the time of when the snapshots occur, i.e. engine run, engine start, etc.

3. Please provide the status messages associated with the snapshots.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

4. Please provide a photo of the parameters recorded in the snapshot.

Final Action

When released, incorporate MDS block point 2, via Service Bulletin 737-31-1929.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: June 2017 (Completed)

Solution Selected: May 2019 (Completed)

Change Committed (PRR 3M0203): Jun 2019 (Complete)

Production Incorporation Available: 737-10 ATC. See 737MAX-FTD-31-23002

Service Bulletin 737-31-1929 Release Schedule Available via 737MAX-FTD-31-23002

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-31-1929		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-19001		
Fleet Team Digest Article (FTD)	737MAX-FTD-73-19001		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-18004		
Maintenance Tip (MT)	737 MT 31-019		01/26/2018
Fleet Team Digest Article (FTD)	737MAX-FTD-36-19001		
Production Revision Record (PRR)	3M0203		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-23002		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991