FLEET TEAM DIGEST

737MAX-FTD-31-19001

Issue Title : Intermittent DPC-2 Internal Faults

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
01/08/2019	08/27/2026	07/09/2026
Estimated Completion Date	**Next Update Date**	

Revision Description

Interim action has been updated to remove the recommendation to deselect the Flight Path Vector (FPV).

Applicability

All 737MAX Airplanes.

Description

Boeing has received reports from multiple operators seeing the First Officer's displays blinking momentarily then returning to normal. The "DSPLY SOURCE 2" message on the Primary Flight Display (PFD) or the "VTK" flag on the Navigation Display (ND) may also be displayed at this time.

On the ground, the "DPC 2" status message and "31-00242 DPC-2 HAS AN INTERNAL FAULT" maintenance message are recorded in Fault History. The "DPC CROSSTALK BUS" status message and correlated crosstalk maintenance message(s) noted below may also be present in Fault History.

- MM 31-00271
- MM 31-00281
- MM 31-00291
- MM 31-00371

Collins Aerospace has been able to reproduce the issue and has identified root cause. The observed behavior is due to the Graphics Engine within the Display Processing Computer (DPC) resetting to recover from an internal fault.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Status

Collins Aerospace has been able to reproduce the issue in their labs and have identified a solution.

A fix is being implemented in the next Max Displays System (MDS) Blockpoint (BP) Release, MDS BP 2, available via Service Bulletin 737-31-1929.

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2 and a list Fleet Team Digest (FTD) articles that are also addressed by the MDS BP 2 release.

Interim Action

On ground, operators should check for active maintenance messages.

If maintenance message 31-00242 is active, the maintenance crew should complete the corresponding IFIM Task 31-65-00-810-860 before addressing any other ATA 31 maintenance messages. Then, maintenance crews should continue to troubleshoot any other active ATA 31 maintenance messages per the IFIM.

If no ATA 31 maintenance messages are active, no further action is necessary as the unit has self-recovered.

Final Action

When available, incorporate Max Displays System (MDS) BlockPoint (BP) 2 Release, MDS BP 2.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Nov 2018 (Complete)

Solution Selected: Jan 2019 (Complete)

Change Committed (PRR 3M0203): Jun 2019 (Complete)

Production Incorporation: See 737MAX-FTD-31-23002

Service Bulletin 737-31-1929 Release Schedule Available via 737MAX-FTD-31-23002

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-31-23002		
Production Revision Record (PRR)	3M0203		
Fleet Team Digest Article	737MAX-FTD-31-18004		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

(FTD)			
Fleet Team Digest Article (FTD)	737MAX-FTD-31-18005		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-21005		
Service Bulletin (SB)	737-31-1929		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-19001		
Fleet Team Digest Article (FTD)	737MAX-FTD-49-18001		
Fleet Team Digest Article (FTD)	737MAX-FTD-80-18001		

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991