FLEET TEAM DIGEST

737MAX-FTD-31-19002

Issue Title : Missing ACMS Takeoff Reports

Airplane Model	ATA	Minor Model(s)
737MAX	3131-22	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
03/21/2019	04/23/2019	04/19/2019

Estimated Completion Date	Next Update Date

Revision Description

Added Production Incorporation Line Position 7575 and Service Letter 737-SL-31-073 release date April 19, 2019.

Applicability

737 MAX Airplanes with Baseline Application for 737MAX, Part Number (P/N) BCG39-L200-0001.

Description

The Baseline Takeoff Report B44 as defined in the 737MAX Boeing Baseline Airplane Condition Monitoring System (ACMS) System Requirements Document (SRD) D243A301 Section 8.33 has been identified to be missing frequently when the Baseline Application for 737MAX, P/N BCG39-L200-0001 is installed on the Teledyne Digital Flight Data Acquisition Unit (DFDAU) Part Number (P/N) 2245000-101.

Status

Through data analysis, the missing Baseline Takeoff B44 reports generally happened at airports with runways at altitudes above 500ft. The issue was confirmed in Boeing Avionics Lab by flying the following flight scenarios: When flying from KBFI at an altitude of 21ft to KPAE at an altitude of 606ft, the takeoff report is triggered normally. When flying from KPAE at an altitude of 606ft to KBFI at an altitude of 21ft, the takeoff report is missing.

The root cause has been confirmed to be the new report closure logic with 500ft as the limit, which is erroneously executed when the airplane takes off from a runway at or above 500ft altitude.

Boeing will release a new Baseline Application for 737MAX, P/N BCG38-L200-0011 on March 29, 2019 to resolve this issue. The Service Letter 737-SL-31-073 737MAX DFDAU ACMS Baseline Update with instructions to retrofit BCG38-L200-0011 was released on April 19, 2019.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

Until the new software Baseline Application for 737MAX, P/N BCG38-L200-0011 is released, the following options are available to mitigate the issue:

If Baseline Application for 737MAX, P/N BCG39-L200-0001 has already been installed, please change the value of the Modifiable Constant “B29ALIM”. The recommendation is to set “B29ALIM” to an altitude value of 300 feet greater than the highest altitude airport to which it operates.

To make the change remotely, this is the ACARS uplink command syntax for setting the “B29ALIM” to an altitude of 2000 feet:

DFD

AN .N7X7BI

- XCM B B29ALIM 2000

To set the “B29ALIM” to an altitude of 2000 feet via the MCDU:

1. Select AMCS

2. Select [L5] REPROGRAM

3. Select [L2] MODIFY CONSTANT

4. Select [L3] CHANGE CONSTANT

5. Enter B29ALIM/B and select [L1]

6. Enter 2000 and select [L2]

7. Select [L5] to SAVE

If Baseline Application for 737MAX, P/N BCG39-L200-0001 has not yet been installed, please continue to use the previous software version Baseline Application for 737MAX, P/N BCG38-L200-0000, until the new Baseline ACMS software version is released.

Additional information on the Baseline Application for 737MAX, P/N BCG39-L200-0001 can be found in Service Letter (SL) 737-SL-31-068. Additional information on the Baseline Application for 737MAX, P/N BCG38-L200-0000 can be found in SL 737-SL-31-067-A.

Final Action

A new Baseline Application for 737MAX, P/N BCG38-L200-0011 was released on March 29, 2019. The Service Letter 737-SL-31-073 737MAX DFDAU ACMS Baseline Update with instructions to retrofit 737MAX, P/N BCG38-L200-0011 was released on April 19, 2019.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Root Cause Established: 18-FEB-19

Solution Selected: 22-FEB-19

Change Committed: 22-MAR-19

Production Incorporation: Line Position 7575

Service Letter 737-SL-31-073 Available: 29-APR-19

Parts Available: 29-MAR-19

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	737-SL-31-067	A	07/24/2018
Service Letter (SL)	737-SL-31-068		01/31/2019
Service Letter (SL)	737-SL-31-073		
Other	D243A301 ACMS SRD		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Digital Flight Data Acquisition Unit (DFDAU)	2245000-101	Teledyne	
Baseline Application for 737MAX	BCG39-L200-0001		
Baseline Application for 737MAX	BCG38-L200-0011		
Baseline Application for 737MAX	BCG38-L200-0000		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991