FLEET TEAM DIGEST

737MAX-FTD-31-20002

Issue Title : 737MAX AIRPLANE CONDITION AND MONITORING SYSTEM (ACMS) REPORT ISSUE

Airplane Model	ATA	Minor Model(s)
737MAX	3131-00	-7, -8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
12/15/2020	07/13/2023	06/27/2023
Estimated Completion Date	**Next Update Date**	
11/26/2023	09/25/2023	

Revision Description

Added 737MAX-FTD-31-23001 (ACMS Software Updates) to the references.

Updated Change committed to reflect release of ACMS Database software.

Revised final action to reflect the ACMS database software release.

Description

Airplane Condition and Monitoring System (ACMS) report B07 Underpressure, Overpressure, Temperature Manifold (TM) High and TM Low (B07) is triggering more than expected.

Service Letter, 737-SL-31-076C references the ACMS Baseline Application for 737 MAX, P/N BCG3A-L200-0002.

This software upgrade added several new reports including the B07 Underpressure, Overpressure, Temperature Manifold (TM) High and TM Low Report.

The intent of this report is to increase data capture opportunities and provide precursors for Integrated Air System Controller (IASC) faults.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

This report is for trending purposes only, there is no maintenance action required if this report triggers.

Status

The B07 report is triggering more than expected and causing increased over reporting.

Interim Action

Boeing recommends disabling the B07 report remotely with this command, "XRD 0 B07 D".

Boeing also recommends disabling the B07 report downlink with this command, "XDL 0 B07 D".

For AHM customers the uplink is labeled “ACMS – Disable Baseline B07 Report Downlink"

To do on-wing instructions reference AMM TASK 31-31-22-860-801. In the AMM step (5) that selects the appropriate Left (Line Select Key) instead select the appropriate Right LSK. Selecting [R1], [R2], [R3], [R4], or [R5] this will disable automatic downlinks of the selected report.

Note: If automatic downlink of the report is disabled, the number of flights field will display “0 FLTS”.

Boeing updated AMM 31-31-22-860-038, which added steps to disable reports.

Final Action

Boeing will update the report trigger in the next baseline ACMS software which is part of 737MAX-FTD-31-23001 Block Point 1.3.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Root Cause Established: May 2021 (Complete)

Solution Selected:June 2021 (Complete)

Change Committed:September 2023

AMM Revised: May 2021 (Complete)

Production Incorporation:TBD

Service Bulletin Available:TBD

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-31-23001		
Service Letter (SL)	737-SL-31-076-C		
Aircraft Maintenance Manual (AMM)	31-31-22-860-801		05/15/2020

Related Categories

- New Equipment : Information on new parts available now or soon to be introduced

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991