FLEET TEAM DIGEST

737MAX-FTD-31-21001

Issue Title : ACARS Printer Failure

Airplane Model	ATA	Minor Model(s)
737MAX	3133-00	-7, -8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
04/19/2021	02/27/2026	01/19/2026
Estimated Completion Date	**Next Update Date**	

Revision Description

Component Service Bulletins AM42905539-31-04 and -05 have been reviewed by Boeing and published by Astronova.

Applicability

All 737 MAX airplanes.

Description

Operators are reporting failures of Astronova Printer Part Number (PN) AM42905539. The most common cause were attributed to the motor stalling and power supply failure. Product improvements were formulated to address these causes of failures. Astronova published two Component Service Bulletin, CSB AM42905539-31-04 and CSB AM42905539-31-05 to improve the performance and reliability of the printer.

CSB AM42905539-31-04 deals with the power supply issue. The COTS DC-DC power module currently installed on the printer's power interface PCB is failing while mounted in the airplane. Analysis provided by the power module manufacturer indicates that the input pins have shorted. The change will consist of a redesign of the power interface PCB which will remove the Vicor module and replace it with DC-DC converter designed by Astonova.

CSB AM42905539-31-05 deals with the motor stall due to a belt damaged caused by paper jam. The paper will be wrapped up with the drive roll and cause the drive roll to stop spinning and the motor will keep trying to move and strip the teeth off the belt. An optical sensor will be used to monitor the movement of the drive roll in coordination with a gear that is attached to the roll. If the sensor detects that the roll is not moving during a print job, the printer will stop the motor and illuminate PAPER on the front panel.

Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Component Service Bulletins AM42905539-31-04 and -05 have been reviewed by Boeing and published by Astronova.

Interim Action

No interim actions required.

Final Action

Component Service Bulletins AM42905539-31-04 and -05 were submitted by Astronova Inc. to Boeing and have been reviewed. The repair solution is now certified to address failures that was seen and experienced in-service. Operators will also get notification from the supplier regarding the procedure of the repair process. Boeing recommends operators to reach out to Astronova Inc through the following link, www.aerospace.astronovainc.com, to determine how to route currently installed printers to Astronova Inc.

Milestones

Component Service Bulletin Available: October 9, 2025

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	Component SB AM42905539-31-04		
Service Bulletin (SB)	Component SB AM42905539-31-05		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
AM42905539		AstroNova	

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991