FLEET TEAM DIGEST

737MAX-FTD-31-21004

Issue Title : 737MAX DIGITAL FLIGHT DATA AQUISITION UNIT (DFDAU) RESET OF AIRPLANE CONDITION AND MONITORING SYSTEM (ACMS) NON-VOLATILE MEMORY (NVM)

Airplane Model	ATA	Minor Model(s)
737MAX	3131-00	-7, -8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
10/18/2021	12/21/2023	12/18/2023
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated Status, Final Action, and Milestones to reflect availability of the new TSS update. There will not be any further updates to this FTD as the issue has been resolved with the release of this new software. Moving this FTD to closure.

Description

Boeing is aware of operators experiencing a reset of the DFDAU ACMS NVM. This includes operator modifiable settings such as, ACMS Report Generation Status, Reports Downlink Configuration, System Parameters, Modifiable Constants, and Unlimited User Parameters control by logic. The reset is causing the automatic downlinks that have been set up by operators to become disabled and the ACMS reports stop downlinking as expected. This issue impacts all partitions, including Baseline and Airplane Health Management (AHM) ACMS software partitions, which prevents the respective reports from being received by AHM, FHM, and customers. Additionally, operators with Weather and Turbulence license keys on the Service Engineering partition gets reset.

Status

Teledyne and Boeing have determined the Target System Software (TSS) incorrectly determines that its Cyclic Redundancy Check (CRC) is different than the previously known TSS CRC. This would happen during normal operation when a new TSS (DFDAU ACMS OPS) is loaded. Teledyne determined that the task that checked the CRC was performing this check before the task that read the old CRC from RAM posted it to shared memory.

Boeing has released a TSS update (31 DFDAU ACMS OPS P/N: TDY4E-7095-1805) which resolves this issue. See 737-SL-31-086 for details on the software update.

Interim Action

When an operator is missing any expected ACMS report downlinks, Boeing recommends enabling the downlinks again via ACARS, LSAPL or per AMM Task 31-31-22-860-801. Also, check AMM Task 31-31-22-860-804 as this configures airplane to enable generation of ACMS Reports. In addition, reference flowcharts 2, 3, and 4 of 737-SL-46-038-B, which provide more

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

information on the ACMS, AHM and baseline ACMS reports.

To enable downlinking of ACMS reports via ACARS, reference 737-SL-46-037-A, page 3 and Attachment I of 737-SL-31-065-E, which provides instructions on how to configure the AHM ACMS reports for Recording and Downlinking.

Additionally, when an NVM reset is triggered, the unit conversion defaults to standard settings (LBS). There is no uplink command to change the setting so the units can only be changed on wing via the MCDU. Affected parameters and information on unit conversion can be found in D243A301.

If Standards Units (LBS) is desired then No Action Required after an NVM reset. If Metric (Kg) is desired use the following steps:

From the DFDAU Main Menu, select Configuration (L1)

From DFDAU Configuration menu, select Initialization (L3)

From DFDAU Initialization menu, select (Unit Conversion (L3)

From Unit Conversion page, select METRIC (L3) and confirm (R3)

Final Action

Boeing recommends updating the Target System Software (TSS) on the DFDAU via SB 737-31-2130. The TSS is installed on the airplane as 31 DFDAU ACMS OPS.

The new TSS has been released in ACMS Block Point 1.4 (See 737MAX-FTD-31-23001 for details on the BP 1.4 release). 737-SL-31-086 and SB 737-31-2130 have been released for this software update (TDY4E-7095-1805).

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established:May 2022 (Complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Solution Selected:July 2022 (Complete)

Change Committed:November 2022 (Complete)

Production Incorporation: Line Number 8920

Service Bulletin Available: December 2023 (Complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	737-SL-31-065-E		
Service Letter (SL)	737-SL-46-038-B		
Service Letter (SL)	737-SL-46-037-A		
Aircraft Maintenance Manual (AMM)	31-31-22-860-804		05/15/2021
Other	Teledyne SL2245000 NO.1	REV 4	03/04/2021
Aircraft Maintenance Manual (AMM)	31-31-22-860-801		05/15/2021
Fleet Team Digest Article (FTD)	737MAX-FTD-31-23001		
Service Bulletin (SB)	737-31-2130		
Service Letter (SL)	737-SL-31-086		

Related Categories

- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991