FLEET TEAM DIGEST

737MAX-FTD-31-21005

Issue Title : Missing Hi-Lo Chime After Initial New .ATC Message Annunciation

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
03/27/2022	11/26/2025	11/03/2025
Estimated Completion Date	**Next Update Date**	

Revision Description

There is an update to the Milestone timeline for 737MAX-FTD-31-23002. This FTD will be closed. Please refer to 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2.

Description

There is no aural chime upon FMC .ATC (*ATC) message uplink if there is currently a new or open FMC *ATC message.

Background

This issue was initially reported in the fleet in October 2017. Boeing testing revealed the aural chime for FMC *ATC messages is not occurring if a previous FMC *ATC message is new or open. For example, if Displays receives an initial FMC *ATC uplink, *ATC will be displayed on the Engine Indication (EI) page and the associated aural chime will occur. However, if this message is left unread or has not yet been responded to and another uplink occurs, *ATC will remain displayed on the EI page, but the associated chime will not occur.

Status

A fix is being implemented in the next Max Displays System (MDS) Blockpoint (BP) Release, MDS BP 2, available via Service Bulletin 737-31-1929.

In addition, please note that that the issues described in the following Fleet Team Digest (FTD) articles are also addressed by the MDS BP 2 release:

[1] 737MAX-FTD-31-18004

[2] 737MAX-FTD-31-18005

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

[3] 737MAX-FTD-31-19001

[4] 737MAX-FTD-80-18001

[5] 737MAX-FTD-49-18001

Interim Action

Be aware there will be no aural chime upon FMC *ATC message uplink if there is currently a new or open FMC *ATC message. It is recommended that crews read and respond to their *ATC messages as they are received to avoid this situation.

Final Action

When available, operators to incorporate Max Displays System (MDS) BlockPoint (BP) 2 Release, MDS BP 2.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Mar 2018 (Completed)

Solution Selected: Aug 2019 (Completed)

Production Incorporation: Please refer to 737MAX-FTD-31-23002 for the current status of MDS BP 2 production incorporation.

Service Bulletin 737-31-1929: Release Schedule Available via 737MAX-FTD-31-23002

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-31-23002		
Fleet Team Digest Article (FTD)	737MAX-FTD-49-18001		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-18004		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-18005		
Fleet Team Digest Article (FTD)	737MAX-FTD-31-19001		
Production Revision Record (PRR)	3M0203		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Service Bulletin (SB)	737-31-1929		
Fleet Team Digest Article (FTD)	737MAX-FTD-80-18001		

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991