FLEET TEAM DIGEST

737MAX-FTD-31-22001

Issue Title : Erasable Status Messages with NFS Failure

Airplane Model	ATA	Minor Model(s)
737MAX	3100-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
02/15/2022	06/29/2022	02/23/2022

Estimated Completion Date	Next Update Date

Revision Description

Updated Interim Action and Milestones to reference Revision 1 of 737-MT-31-020 which was released on 8-Apr-2022. Final action was revised to mention that AMM/FIM revisions have been completed.

Description

737MAX operators have reported impacts to maintenance when the Network File Server (NFS) is not functional. The NFS hosts the Onboard Network System (ONS)/Onboard Maintenance Function (OMF). When the NFS/ONS/OMF is inoperative or on the Minimum Equipment List (MEL), maintenance is unable to conduct several Aircraft Maintenance Manual (AMM) and Fault Isolation Manual (FIM) tasks. Current troubleshooting procedures for a majority of 737 MAX systems rely exclusively on OMF availability. The inability to conduct AMM/FIM checks which use the OMF may require alternate procedures to determine if an airplane can be returned to service. This issue has resulted in schedule interrupt events including flight cancellations when an airplane was unable to exit a hangar check due to the inability to complete return to service checks.

Status

Operators have asked for guidance on how to verify if a fault with an erasable status message has been fixed while operating with an inoperative NFS.

Interim Action

Boeing released Maintenance Tip 737-MT-31-020-R1 on 8-Apr-2022 which provides a list of status messages that are latched within the Max Display System (MDS) and what action would be needed to verify the condition has been fixed after erasing the status message in cases where an airplane is operating with an inoperative NFS. In cases where a status message is latched by another Line Replaceable Unit (LRU), 737-MT-31-020-R1 includes a list to verify the system is operable when the NFS is inoperative. Note that the "Dispatch Relief" column indicates if the item can be placed on MEL.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

Boeing has updated both the AMM and FIM to include the guidance contained within Maintenance Tip 737-MT-31-020-R1. An Observed Fault has been added to the FIM which references AMM Task 46-13-02-860-806 that includes the list of erasable status messages and what action is needed to verify that the condition has been fixed after maintenance is complete. Boeing has incorporated these changes in the 15-May-2022 revision of the AMM/FIM.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

737-MT-31-020 Release: 28-Jan-2022

737-MT-31-020-R1 Release: 8-Apr-2022

AMM Revisions: 15-May-2022

FIM Revisions: 15-May-2022

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-46-19001		
Maintenance Tip (MT)	737-MT-31-020		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in
  Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs.
  High failure rate of costly/critical systems
- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991