FLEET TEAM DIGEST

737MAX-FTD-31-22002

Issue Title : 737MAX FDR OFF LIGHT FLASH

Airplane Model	ATA	Minor Model(s)
737MAX	3131-12	-8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
08/03/2022	10/15/2023	09/21/2023
Estimated Completion Date	**Next Update Date**	

Revision Description

Closing this FTD, AMM updated.

Description

The purpose of this Fleet Team Digest Article is to inform operators of a condition discovered during certification on the new Honeywell Flight Data Recorders (FDR) Part Number (P/N) 69004750-001, where the FDR OFF light does a quick flash when going into TEST mode, and also flashes when going back into NORM state before getting the steady OFF light indication after a few second delay. This observed condition is seen while the airplane is on ground with no engines running. When maintenance initializes an FDR test from the Flight Recorder and Mach Airspeed Panel (P5-19), the FDR OFF light will flash.

Status

This is an observed condition that does not require any maintenance action. Boeing has added a note to AMM TASK 31-31-12-860-004, which explains that on airplanes equipped with the Honeywell FDR P/N: 69004750-001, the FDR OFF light quickly flashes when going into TEST mode, and also flashes when going back into NORM state before getting the steady OFF light indication after a few second delay.

The flashing light note was originally added to the AMM on 15-JAN-2023, which applied to all FDRs. However, on 15-MAY-2023, the AMM note has been updated to specify that only the Honeywell FDR P/N: 69004750-001 exhibits this behavior.

Interim Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

N/A

Final Action

Boeing updated the AMM TASK 31-31-12-860-004 to inform operators equipped with the Honeywell FDR P/N: 69004750-001 of the FDR OFF light behavior.

Milestones

Aircraft Maintenance Manual Update: 15-MAY-2023 (Complete)

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991