# FLEET TEAM DIGEST

## 737MAX-FTD-31-23001

**Issue Title :** Digital Flight Data Acquisition Unit (DFDAU) Airplane Condition Monitoring System (ACMS) Software Updates - Block Point 1.3 and 1.4

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3131-00 | -7, -8, -8200, -9 |
| **Other Model(s)** | **ECCN** | |
| | 9E991 | |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 04/13/2023 | 11/12/2024 | 11/06/2024 |
| **Estimated Completion Date** | **Next Update Date** | |

## Revision Description

Updated all milestones to complete. Recommend closure of this FTD.

## Description

This Fleet Team Digest (FTD) article provides background information and status of upcoming Digital Flight Data Acquisition Unit (DFDAU) Airplane Condition Monitoring System (ACMS) software updates.

737 MAX operators have experienced several different failure modes with the DFDAU. Boeing has opened a Service Related Problem (SRP) for the list of in-service issues and DFDAU enhancements. A subset of the issues in the SRP will be incorporated in two different Block Point software upgrades.

Block Point 1.3 is updating the ACMS Baseline Database software (31 DFDAU ACMS BASELINE DB) and Digital ACMS Recording (DAR) Airline Modifiable Information (AMI) (31 DFDAU ACMS DAR AMI). Block Point 1.4 is updating the ACMS Operational Software (31 DFDAU ACMS OPS). Below are the major fleet-impacting issues that will be fixed in these software updates.

| Description | Current P/N | Future P/N |
|---|---|---|
| ACMS Baseline DB | BCG3A-L200-0002 | BCG3B-L200-0003 |
| ACMS DAR AMI | BCG24-R200-0002 | BCG25-R200-0003 |
| ACMS OPS | TDY4F-4095-1804 | TDY4E-7095-1805 |

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

*Note: Future P/Ns are subject to change*

Block Point 1.3:

1. Address extraneous ECS Under-Overpressure Temperature Manifold High and Low reports (B07)

2. Fix Cruise and Climb data misalignment in ACMS reports

3. Update Engine Electronic Controller (EEC) maintenance words in ACMS Engine reports

4. Fix Auxiliary Power Unit (APU) cycle count in ACMS reports and DAR map

5. Edit to all baseline ACMS reports to include the year in the report header

6. DAR map update

Block Point 1.4:

7. Fix ACMS report generation and downlink settings being reset (NVM Reset)

8. Fix CFast card date and timestamp misalignment

9. Fix an issue causing the ACMS prompt not displaying on MCDU (ACMS Application Exception)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

10. Address an issue causing ACMS reports to stop generating (ACMS Application Exception)

11. Fix intermittent ACMS reports not being transferred to ONS

12. Allow negative modifiable constant values

13. Fix Real Time DITS (ARINC 429) report (requested by uplink)

14. Increase memory allocation to allow larger baseline and operator application

## Status

The new ACMS Baseline Database, DAR AMI, and ACMS Operational Software updates are now released to the fleet for retrofit. Production incorporation cut in at Line Number 8920.

## Interim Action

Boeing recommends operators reference 737MAX-FTD-31-21004 when experiencing a NVM reset of the DFDAU.

Boeing recommends operators reference 737MAX-FTD-31-20002 when experiencing more than expected B07 ACMS reports.

While troubleshooting ACMS issues, Boeing recommends operators reformat the internal DFDAU memory. This can be accomplished using the 'Clear ACMS' feature on the MCDU (per "Instructions for Clearing the ACMS Memory" attachment). Operators may discover the ACMS prompt is missing from the MCDU. If this is the case, there is another method to reformat the internal DFDAU memory. When a new ACMS OPS software part is installed, the DFDAU will format the internal memory as part of that installation. Operators will need to load a different version of the 31 DFDAU ACMS OPS software part (this is sometimes referred to as the DFDAU Target System Software (TSS)). If this restores the MCDU ACMS prompt, then the correct ACMS OPS software can be re-installed and the DFDAU report settings reconfigured.

Note: When the internal DFDAU memory is reformatted, all reports stored on the DFDAU's internal memory will be lost.

Boeing recommends the following troubleshooting steps:
1) Load an older ACMS OPS software (TDY48-7095-1803) to the DFDAU
2) Power cycle the DFDAU and power cycle the NFS
3) Ensure the MCDU ACMS prompt stays available
4) Reload the current ACMS OPS software (TDY4F-7095-1804) to the DFDAU

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

5) Restore the desired ACMS configuration for baseline and AHM reports
5a) Ref AMM TASK 31-31-22-860-804 to enable/disable report generation
5b) Ref AMM TASK 31-31-22-860-801 to enable/disable report auto-downlinking

Boeing is aware that this will not solve all of the missing ACMS issues, if the following troubleshooting steps do not clear the issue then please reach out to Boeing via an Service Request for additional assistance.

Boeing is currently evaluating this situation further to provide proper guidance and will update the FIM item 31-31-00-810-893 (MCDU ACMS Menu Selection Does Not Show) accordingly.

## Final Action

**Block Point 1.3 - ACMS Baseline Database and DAR AMI**

737-SL-31-084, 737-SL-31-085

**Block Point 1.4 - ACMS Operational Software**

737-SL-31-086, SB-737-31-2130

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: September 2022 (Complete)
Solution Selected: November 2022 (Complete)

BP 1.3 Parts Available: December 2023 (Complete)

BP 1.4 Part Available: December 2023 (Complete)

Production Incorporation: Line Number 8920 (Complete)
Service Bulletin Available: 737-31-2130

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-20001 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-20002 | | |

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

| | | | |
|---|---|---|---|
| Fleet Team Digest Article (FTD) | 737MAX-FTD-31-21004 | | |

## Parts List

| Part Name | Boeing Part Number | Supplier Name | Supplier Number |
|---|---|---|---|
| DFDAU | 2245000-101 | Teledyne | 2245000-101 |

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- New Equipment : Information on new parts available now or soon to be introduced
- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

## Attachments:

a) Instructions for Clearing the ACMS Memory

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991