FLEET TEAM DIGEST

737MAX-FTD-31-23004

Issue Title : Takeoff Alert Inhibit Option

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7, -8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
06/14/2023	09/04/2026	01/07/2026
Estimated Completion Date	**Next Update Date**	

Revision Description

There is an update to the Milestone timeline for 737MAX-FTD-31-23002. This FTD will be closed. Please refer to 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2.

Applicability

All 737MAX Airplanes.

Description

Boeing has determined that there is an issue with Option Selection Software (OSS) parameter OSS_TO_ALERT_INH_800FT.

Background

The Takeoff Alert Inhibit is designed to inhibit the blinking for Engine Alert Messages as described in the Flight Crew Operations Manual (FCOM) Chapter 7 (Engines, APU), Section 10 (Controls and Indicators: Crew Alerts). The Inhibit feature is designed to minimize pilot distractions from 80 knots (kts) up to 400 feet (ft) Radio Altitude (RA) by disabling the OSS parameter above and inhibiting blinking up to 400 ft RA. However, it was determined that the parameter was inverted such that the Inhibit is enabled through 800 ft RA.

Note:
- The Engine Alert Messages will still annunciate and parent aircraft requirements are still met; requirements do not specify either blinking or inhibiting behavior of crew alerting.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

- This issue was determined not a safety issue.

Status

Boeing will publish a Flight Crew Operations Manual Bulletin (OMB) to reflect the current differences between design and actual behavior.

Applicable FCOM Volume 2 (V2) systems descriptions are also being amended to reflect these changes targeting a November '23 release.

The final fix will be available as part of the next MAX Display System (MDS) BlockPoint (BP) release, MDS BP 2.

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2 and a list Fleet Team Digest (FTD) articles that are also addressed by the MDS BP 2 release.

Interim Action

Boeing has identified two interim courses of action:

(1) Operators may continue to fly with the OSS parameter inversion of 800 ft RA.

If this course of action is chosen, operators should consider proactively communicating with flight crew that blinking of engine alerts will be inhibited at a different range (up to 800 ft RA instead of up to 400 ft RA) than as described in FCOM Chapter 7.10.

Be aware that the OSS parameter OSS_TO_ALERT_INH_800FT is designed for affected aircraft to inhibit during takeoff from 80 Knots Indicated Airspeed (KIAS) to 400 ft RA as described in the FCOM, or 30 seconds after reaching 80 kts, whichever occurs first; however, the inhibit is currently active up to 800 ft RA, or 30 seconds after reaching 80 kts.

(2) An optional Boeing Service Bulletin (SB 737-31-2108) will be available for in-service airplanes flying with MDS OPS (Operational Program Software) SW BP 1.5.1 to revert to the intended 400 ft RA inhibit configuration until the release of MDS BP 2.

When available, please submit a Service Request via My Boeing Fleet or contact your Field Service Representative and reference PRR 3M9900-100R and/or SB 737-31-2108.

Note: DPC OSS P/N BCG2F-MDS0-0232 and (-0XXX) onwards already include the fix that would be implemented with SB 737-31-2108.

Final Action

When available, incorporate Max Displays System (MDS) BlockPoint (BP) 2 Release, MDS BP 2. This will revert the behavior to the intended 400 ft RA inhibit.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2.

Milestones

Note: Target dates are based upon currently available status and are subject to change.

Root Cause Established: Completed
Solution Selected: Completed
Change Committed: PRR3M9900-100R
Production Incorporation: See 737MAX-FTD-31-23002
Optional Service Bulletin 737-31-2108 Available: As Requested
Service Bulletin 737-31-1929: Release Schedule Available via 737MAX-FTD-31-23002

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991