FLEET TEAM DIGEST

737MAX-FTD-31-25001

Issue Title : Master Caution 1864 Lamp Dimensions

Airplane Model	ATA	Minor Model(s)
737MAX	3151-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737, 737NG	9E991

Originated Date	Last Revised Date	Created On
10/01/2025	10/01/2025	08/27/2025

Estimated Completion Date	Next Update Date

Applicability

All 737 MAX Airplanes

Description

Operators of 737 Classic and 737NG aircraft previously experienced nuisance indications of the master caution assembly. The light illuminates when it is not supposed to and has created several flight delays. Boeing and the supplier, Korry, determined that the 1864 lamp within the master caution assembly is the main cause of these nuisances. Since the 737 MAX uses the same master caution assembly, Boeing is releasing this Fleet Team Digest Article to provide the same recommendation to the 737 MAX fleet.

Status

Boeing and Korry previously completed an evaluation on current master caution assemblies. It was determined that the 1864 lamps within the master caution assembly vary in dimensions among suppliers. Korry decided that the bulb dimensions can vary too much among suppliers and therefore they cannot re-design the assembly to accommodate for this. Boeing has not received any recent reports of Master Caution nuisances caused by 1864 lamps.

Interim Action

N/A

Final Action

The solution to the nuisance issue is to avoid 1864 lamps with a longer metal base and/or a longer bayonet. The longer metal base can contact the sides of the socket within the master caution assembly which can complete the circuit and cause the light to illuminate. Boeing recommends avoiding all lamps with a metal base that is longer than 0.344" in length. Please see the attached picture for further information.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

It is recommended that operators screen their bulbs for the proper dimensions and switch suppliers if any bulbs from the current supplier are having issues within the master caution assembly.

Milestones

N/A

Operator Action

If an operator is having master caution/fire warning nuisance faults then the 1864 lamps within the assemblies should be inspected and/or replaced. Using the bulbs with the proper dimensions could help alleviate this issue. It has been shown by some operators that GE1864 lamps tend to have the best results in these assemblies.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Illustrated Parts Catalog (IPC)	33-11-00-50		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Bulb	1864		
Indicator Light Assembly	088-515-1031-106	Koito	

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- In Service Occurrences : null

Attachments:

a) 1864 metal base length

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991