FLEET TEAM DIGEST

737MAX-FTD-32-17004

Issue Title : Nose Gear Tires Contact Nose Gear Door Center Hinge Fitting

Airplane Model	ATA	Minor Model(s)
737MAX	3220-00	-7, -8, -9
Other Model(s)	**ECCN**	
737, 737NG	9E991	

Originated Date	Last Revised Date	Created On
05/02/2017	05/02/2017	04/11/2017
Estimated Completion Date	**Next Update Date**	

Applicability

All 737MAX airplanes.

Description

Some operators have reported finding evidence that the nose gear tires have been contacting the center hinge fitting of the nose gear doors on 737-series airplanes. See attached photo.

In one case, the airplane also experienced unusual noises during nose wheel spin down after nose gear retraction and a loud banging noise during nose gear extension.

Maintenance discovered that the NLG shock strut was under-serviced. The under-serviced strut allowed the shock strut inner cylinder to disengage the internal centering cam during retraction which then allowed the nose gear tires to turn to one side. If the tires are not pointed straight ahead, they can contact the nose gear doors or hinge fittings. The unusual noise heard during gear retraction are the tires rubbing on the door or hinge fitting.

Proper servicing of the nose gear shock strut with oil and nitrogen per the AMM corrected the problem.

Status

n/a

Interim Action

n/a

Final Action

Ensure the nose gear shock strut is properly serviced with oil and nitrogen per AMM 12-15-41.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Aircraft Maintenance Manual (AMM)	12-15-41		

Related Categories

- In Service Occurrences : null

Attachments:

a) Tire Rubs on Center Hinge

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/06/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991