FLEET TEAM DIGEST

737MAX-FTD-32-19003

Issue Title : Safran Landing Systems Nose Wheel - Fractured Flange

Airplane Model	ATA	Minor Model(s)
737MAX	3245-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
03/27/2026	03/27/2026	10/30/2019

Estimated Completion Date	Next Update Date

Applicability

737NG and 737MAX airplanes using Safran Landing Systems nose wheel P/N C20637000 and P/N C20637100.

Description

Between 2016 through 2019, several operators have experienced Safran Landing Systems (SLS), nose wheel cracks on part number C20637000 when installed with bias tires on the 737NG airplanes. In some instances, these cracks resulted in fractures of the nose wheel flange and caused the flange to depart the airplane. See the attachment for typical damage. Thus far, the occurrences have been reported after landing rollout during taxi.

In 2025, an operator experienced a failure of its nose wheel C20637000 where the flange departed the airplane. The damaged hardware was sent to SLS for a metallurgical analysis where it was determined the wheel had multiple microcracks on the fracture faces. The cracks extended from the outer surface toward the inner surface and corrosion was present on the external surface of the rim. This specific wheel accumulated 14,399 Cycles Since New (CSN), 396 Cycles Since Overhaul (CSO), and 33 Cycles Since Installation (CSI). The adjacent nose wheel was also sent to SLS for analysis and no anomalies were found.

Note: Only radial tires can be installed on both C20637000 and C20637100 on 737MAX airplanes.

Status

SLS has performed multiple investigations for each of the returned wheels. It was determined these fractures initiate in the bead seat area of the Inner and Outer Half-Wheel Assemblies. To mitigate the risk of wheel crack propagation, Safran created the following:

- Safan Service Bulletin C20637-32-006. This inspection SB provides instructions to completely check the outer and inner surfaces of the rim by Eddy Current Inspection to make sure that there is no crack initiation point.
- Safran Service Letter SL C20637-32-010. This Service Letter introduces a contour probe, to be used during inspection at overhaul, which improves crack detection.
- SLS CMM 32-49-82 Rev 7 published on September 2021 or later, highly recommend the use of the contour probe kit part number F28318000 or automatic wheel inspection systems to perform the Eddy Current inspection of the bead seat area

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

instead of the pencil probe which may not accurately detect a potential crack(s).
- Safan Service Letter SL C20637-32-011. This Service Letter informs operators to use the contour probe or automatic wheel inspection system to accurately detect cracks on wheel P/N C20637000 and P/N C20637100. The intent of this Service Letter is to inform operators and wheel shops to stop using less effective pencil surface probes for this inspection when performing CMM 32-49-82 subtask 32-49-82-200-002-A01 Paragraph (2).(b) Eddy Current inspection.

Note: The wheel shop that maintained the wheel that failed in 2025 was not using the recommended contour probe kit part number F28318000 or automatic wheel inspection systems to perform the Eddy Current inspection of the bead seat area.

Interim Action

None

Final Action

Boeing and Safran recommend performing the inspection per Safran SB C20637-32-006 and procuring Contour Probe Kit part number F28318000 per SL C20637-32-010 and SL C20637-32-011.

- Safran SB C20637-32-006, issued March 2019.
- SL C20637-32-010, issued October 2019.
- SL C20637-32-011, issued February 2026.

Ensure wheel part numbers C20637000 and C20637100 are repaired or overhauled per Safran Landing Systems CMM 32-49-82 Rev 7 published on September 2021 or later. Repair Orders (RO) to the wheel shops should stipulate to comply with SL C20637-32-010 and SL C20637-32-011 when repairing your wheels.

For further information, contact your local Safran Customer Support Center, CSC -

- Europe: eamecsc.sls@safrangroup.com
- America: americascsc.sls@safrangroup.com
- Asia: asiacsc.sls@safrangroup.com
- China: chinacsc.sls@safrangroup.cn

Milestones

Safran SB C20637-32-006, issued March 2019.

SL C20637-32-010, issued October 2019.

SL C20637-32-011, issued February 2026.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	C20637-32-006		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Component Maintenance Manual (CMM)	SLS CMM 32-49-82		
Service Letter (SL)	C20637-32-010		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Nose Wheel Assembly	10-62237-12	SLS	C20637000
Nose Wheel Assembly	10-62237-62	SLS	C20637100

Related Categories

- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Parts Departing Airplane : Reports of parts departing the airplane in flight

Attachments:

a) SLS Nose Wheel Flange Fracture

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991