FLEET TEAM DIGEST

737MAX-FTD-32-26001

Issue Title : Rotor Rivet Damage on Safran Brake

Airplane Model	ATA	Minor Model(s)
737MAX	3241-41	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
08/11/2026	08/11/2026	07/09/2026

Estimated Completion Date	Next Update Date
07/30/2027	10/16/2026

Applicability

737 MAX airplanes using Safran Landing System (SLS) Carbon Brake Assy P/N C20633000.

Description

As described in the referenced FTD Article, the 737MAX fleet equipped with Safran Landing Systems (SLS) Brake P/N C20633000 Amdt D experienced isolated occurrences of rotor clip cracking at approximately 1,000 flight cycles on average. Following evaluation of the fleet experience, SLS introduced a design improvement to enhance rotor clip robustness. The previous H-style rotor clips were replaced by a new U-style clip design, which addressed the rotor clip cracking condition. Following validation, this design improvement was incorporated into Boeing production and introduced to the in-service fleet through SLS Service Bulletin (SB) C20633-32-025.

It is important to note, the H-style rotor clip/rivet condition previously observed with the fleet is not the same anomaly observed with the recent U-style rotor clip design change. The current damage to the U-style clip appears to be isolated to the rivets only. Boeing and SLS have received a limited number of reports associated with missing or fractured rivet heads. This damage has been reported to rotor one (1) only, and appears to occur between 500 to 1,000 flight cycles. Boeing and SLS are currently reviewing available fleet data to assess whether the new rotor clip design may have any influence on the observed rivet condition and will continue to monitor in-service experience. Please see the attached file for a depiction of the clip design change as well as damage location and examples.

Status

Safran Landing Systems (SLS) is currently investigating rivet-related conditions observed on the new U-clip design. It is important to note that similar rivet conditions had been reported in the fleet prior to this design change.

The ongoing investigation aims to determine whether the new design has any influence on the occurrence rate of these conditions. Preliminary findings indicate that wheel deformation, previously identified as a contributing factor, may continue to be involved.

Boeing will update this article once the investigation is complete and any recommendations or proposed actions from SLS are defined.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

Please note, when the wheel-tire assembly will be installed on the landing gear axle per AMM Task 32-45-11-400-801, it is required to perform an inspection on the brake assembly per paragraph G.(1).(d). Boeing emphasizes the importance of thoroughly inspecting the brake assembly during the removal of the wheel-tire assembly per 737 MAX AMM Pageblock 32-45-11/401, 'Main Landing Gear Wheel And Tire Assembly - Removal/Installation'.

When performing AMM Task 32-41-41-700-803 'Main Landing Gear Brake Inspection (Wheel Removed from the Airplane)', ensure to examine the brake for these types of damage:

- Broken, loose, or missing rivets and clips
- Examine the brake and surrounding area for unusual carbon debris such as chips or small pieces of carbon broken off of the rotors and stators

If damage is found as shown in the attached file within this FTD article, Boeing recommends replacing the brake assembly. If the brake assembly cannot be replaced, Boeing can provide a small number of flight cycles in order to reach the maintenance facility to remove the brake assembly. For such request, please submit a Service Request (SR) to Boeing containing clear and detailed photographs of the brake assembly for review.

Final Action

Final action is pending root cause determination. Once root cause is made available, Boeing will update this article to reflect the findings, Safran Landing Systems' permanent mitigation plan, and Boeing's recommendations for operator actions.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

- Root Cause Established: ECD September 2026
- Solution Selected: ECD TBD

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
In-Service Occurrence Report (ISO)	ISO-32-26-53236		06/03/2026
Fleet Team Digest Article (FTD)	737MAX-FTD-32-22001		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Brake Assy	C20633000	Safran Landing Systems	F6137

Related Categories

- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board

Attachments:

a) Rotor Rivets Attachment Safran

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991