FLEET TEAM DIGEST

737MAX-FTD-32-26002

Issue Title : Rotor Rivet Damage on Collins Brake

Airplane Model	ATA	Minor Model(s)
737MAX	3241-41	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
08/11/2026	08/11/2026	07/09/2026

Estimated Completion Date	Next Update Date
12/11/2026	11/06/2026

Applicability

737 MAX airplanes using Collins Carbon Brake Assy P/N 2-1740-1.

Description

In an effort to reduce the occurrence of wheel and brake binding events, Collins recently introduced a design change to Carbon Brake P/N 2-1740-1 which introduced a cap-style rotor clip to replace the previous floating-style clip. This was implemented into Boeing production and made available to the fleet with the release of Collins Service Bulletin SB 2-1740-32-7. Following the implementation of this SB, Boeing and Collins have received reports from 737MAX operators of damage to the rivets securing the new clips. Failed rivets have been observed on heat sink assemblies with under 600 landing cycles or 25% wear life in average. To date, failed rivets have been limited to rotor position 1 (nearest the piston housing). In a small number of cases, stator 1 also presented minor damage. Please see the attached file for a description of the damage and location.

Status

Collins is conducting an investigation to determine the root cause of the rivet fractures. Preliminary findings suggest high wheel deflection with radial tires is driving relative motion between the rotor clips and torque bars, causing fatigue damage on rivets. Additionally, Collins has proposed a mitigation plan to alleviate operator impacts. Boeing is currently reviewing this proposal and will update this article with more details once the review process is complete.

Interim Action

Please note, when the wheel-tire assembly will be installed on the landing gear axle per AMM Task 32-45-11-400-801, it is required to perform an inspection on the brake assembly per paragraph G.(1).(d). Boeing emphasizes the importance of thoroughly inspecting the brake assembly during the removal of the wheel-tire assembly per 737 MAX AMM Pageblock 32-45-11/401, 'Main Landing Gear Wheel And Tire Assembly - Removal/Installation'.

When performing AMM Task 32-41-41-700-803 'Main Landing Gear Brake Inspection (Wheel Removed from the Airplane)', ensure to examine the brake for these types of damage:

- Broken, loose, or missing rivets and clips
- Examine the brake and surrounding area for unusual carbon debris such as chips or small pieces of carbon broken off of the rotors and stators

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

If damage is found as shown in the attached file within this FTD article, Boeing recommends replacing the brake assembly. If the brake assembly cannot be replaced, Boeing can provide a small number of flight cycles in order to reach the maintenance facility to remove the brake assembly. For such request, please submit a Service Request (SR) to Boeing containing clear and detailed photographs of the brake assembly for review.

Final Action

Final action is pending root cause determination. Once root cause is made available, Boeing will update this article to reflect the findings, Collins' permanent mitigation plan, and Boeing's recommendations for operator actions.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

- Root Cause Determination: ECD August 2026
- Boeing Review of Mitigation Plan: ECD August 2026
- Parts Available to In-Service Fleet: ECD TBD
- Production Incorporation: ECD TBD

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Brake Assy	2-1740-1	Collins Aerospace	97153

Related Categories

- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

Attachments:

a) Rotor Rivets Attachment Collins

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991