FLEET TEAM DIGEST

737MAX-FTD-33-18001

Issue Title : Anti-Collision Light Power Supply Failures

Airplane Model	ATA	Minor Model(s)
737MAX	3344-01	-8, -9

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
03/19/2018	05/03/2018	04/20/2018

Estimated Completion Date	Next Update Date

Revision Description

Added Service Bulletin release information.

Applicability

737 MAX airplanes with anti-collision light power supply P/N 60-4983-3, serial numbers 29559 to 30759.

Description

Boeing has seen failures of the Anti-Collision Light (ACL) power supply P/N 60-4983-3 occurring in-service.

Background

Starting mid-2017, there has been an increase of production and early in-service removals of the ACL power supply P/N 60-4983-3. The majority of the removals are in the upper ACL location.

Status

Honeywell and Boeing performed a root cause investigation and have isolated the root cause of the failures to a transistor failure (Q2 MOSFET) in the circuit card assembly. Due to obsolescence, the supplier recently replaced the Q2 MOSFET with one of the same part number, but with a lower breakdown voltage margin. Electrical overstress of the Q2 MOSFET with a lower breakdown voltage margin is the direct cause of the recent power supply failures. Other contributing causes are: induced noise on Q2 from the xenon lamp is higher on the upper ACL position, and inconsistent conformal coating on the circuit card assembly could induce high voltage on Q2 with condensation.

As corrective action, Honeywell will replace existing Q2 with a higher voltage part, add noise protection, and implement process improvements to ensure conformal coating robustness and increased thickness.

Interim Action

None

Final Action

Production incorporation of the more robust P/N 60-4983-3 assemblies started in March 2018.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Power supplies with serial numbers 30760 and higher have the design improvements implemented.

The range of affected serial numbers is 29559 to 30759.

Honeywell released service bulletin 60-4983-33-0001 to provide retrofit instructions for in-service units.

Milestones

Honeywell Service Bulletin released on 16-April-2018.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	Honeywell 60-4983-33-0001		
Component Maintenance Manual (CMM)	33-44-27		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Strobe Power Supply	S283A305-101	Honeywell	60-4983-3

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991