# FLEET TEAM DIGEST

## 737MAX-FTD-34-18003

**Issue Title :** Honeywell IMMR Fault Messages

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3431-00 | -8 |
| **Other Model(s)** | **ECCN** | |
| | 9E991 | |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 02/19/2018 | 10/31/2018 | 10/31/2018 |
| **Estimated Completion Date** | **Next Update Date** | |

## Revision Description

Status section was revised to include Service Letter release information.

## Applicability

737MAX airplanes utilizing Honeywell IMMR, PN: 69002600-0101

## Description

This FTD provides information regarding AHM fault messages seen for the Honeywell IMMR which appear during cruise, then typically self recovers shortly before landing.

## Background

Reports have been received stating that upon review of AHM data, operators utilizing Honeywell IMMR, PN: 69002600-0101, have experienced events during cruise indicating the following fault messages were active:

34-31001 / MMR-1 HAS AN INTERNAL FAULT

34-61323 / MMR-1 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 1)

34-61324 / MMR-1 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 2)

34-31002 / MMR-2 HAS AN INTERNAL FAULT

34-62323 / MMR-2 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 1)

34-62324 / MMR-2 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 2)

An investigation of these events has been performed. Root cause is due to the unit declaring a fault code for the Localizer DDM Comparison Monitor. The localizer receiver has a main and a monitor path for the deviation computation and the receiver is detecting a disagreement between these paths when the receiver is left tuned to an ILS frequency during cruise where no valid localizer signal is being received. This failure self-clears once a valid localizer signal is detected on the tuned frequency, usually in the terminal area.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Status

A software fix has been developed and certification efforts have been completed with production incorporation on LN 6881. Retrofit Service Bulletin (SB), 737-34-3211, has been developed and was released on 11-JUL-2018.
A related Service Letter to inform operators of this fix has been developed with a 02-NOV-2018 release date.

## Interim Action

No Interim Action Required.

## Final Action

Final Action consists of the release of a Service Letter and Service Bulletin informing operators of the availability and installation authorization of the certified IMMR software fix.

## Milestones

Production Incorporation: LN: 6881 (Delivered 30-APR-2018)

Service Bulletin Available: 11-JUL-2018 (Released)

Service Letter Dated: 02-NOV-2018

## Operator Action

As a temporary resolution operators are recommended to inform flight crews to keep the receiver tuned to a valid VOR frequency during cruise. For cases where these faults are found set, the FIM procedure should be followed and if the operational system test passes, the unit does not need to be removed from the airplane.

## Supplier Information

HONEYWELL INTERNATIONAL INC. 15001 NE 36TH ST REDMOND, WA

98052-5317

## Parts List

| Part Name | Boeing Part Number | Supplier Name | Supplier Number |
|---|---|---|---|
| IMMR | 69002600-0101 | HONEYWELL INTERNATIONAL INC. | |

## Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991