# FLEET TEAM DIGEST

## 737MAX-FTD-34-18004

**Issue Title :** TAT DISAGREE STATUS MESSAGE POSTED ON GROUND

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3461-00 | -7, -8, -8200, -9, -BBJ |

| Other Model(s) | ECCN |
|---|---|
| | 9E991 |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 04/04/2018 | 02/23/2021 | 02/16/2021 |

| Estimated Completion Date | Next Update Date |
|---|---|
| | |

## Revision Description

Updated Final Action and Milestones sections.

## Applicability

All 737 MAX Airplanes below L/N 7735.

## Description

A 737 MAX operator reported having the Total Air Temperature TAT DISAGREE status message displayed while the airplane was on the ground. Per the Flight Management System (FMS) design requirements, this message should not be displayed on the ground.

This status message is displayed on the Maintenance / Status page accessed through the MAX Display System (MDS) Systems Page.

If the TAT DISAGREE status message is set during flight, the amber MAINT light on the aft overhead panel illuminates 30 seconds after landing.

ACRONYMS:

FMS - Flight Management System

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

TAT - Total Air Temperature

## Status

Weather conditions on ground may contribute to this system behavior.

Boeing has coordinated with GE Aviation, the Flight Management System (FMS) supplier, who has agreed to provide a software fix to address this issue.

GE Aviation has initiated a Problem Report (PR-37012) to track their investigation.

GE Aviation will introduce a software fix to address the 'TAT DISAGREE displayed on the ground' issue in the next FMS software upgrade U14.

Boeing has committed Production Revision Record 39146 to incorporate U14 into production 737 MAX airplanes and allow retrofit of U14 into 737 MAX airplanes per Boeing Service Bulletin SB 737-34-3065.

Flight Management Computer (FMC) Upgrade 14.0 Operational Software is to be incorporated into 737 MAX airplanes. Refer to Fleet Team Digest article 737MAX-FTD-34-18005 for further details. All storage airplanes will have U14 installed prior to delivery with the exception of HGS-6000 Heads Up Display System equipped airplanes. HGS-6000 equipped airplanes will continue to get U13 until U14.1 is released. Reference 737MAX-FTD-34-20002 for additional information regarding U14.1.

## Interim Action

The TAT DISAGREE status message displayed on the ground may be considered a nuisance message by the 737 MAX operators until a software fix is implemented.

## Final Action

For non-HGS-6000 Heads Up Display System equipped airplanes, install FMCS Upgrade 14.0 Operational Software.

Airplanes that are equipped with the HGS-6000 will be delivered with the U13 FMC OPS until the U14.1 FMC OPS becomes available. Details related to the U14.1 FMC OPS are provided in 737MAX-FTD-34-20002.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 30 March 2018 (Complete)

Solution Selected: 10 May 2018 (Complete)

Change Committed: 01 June 2018 (Complete)

Production Incorporation: L/N 7887

For non-HGS-6000 Head Up Display System equipped airplanes:

Service Bulletin Available: 9-Dec-2020 (Complete)

Parts Available: 9-Dec-2020 (Complete)

## Operator Action

This is a nuisance Status Message issue for Maintenance personnel awareness/action only. There is no operator action that can be identified at this time.

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Production Revision Record (PRR) | 39146 | | |
| Service Bulletin (SB) | 737-34-3065 | | |
| Other | DPR 37MXFOTV-PR926 | | 03/30/2018 |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-34-18005 | | |
| Fleet Team Digest Article (FTD) | 737MAX-FTD-34-20002 | | |
| Other | GE Aviation PR-37012 | | |

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/08/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991