FLEET TEAM DIGEST

737MAX-FTD-25-17001

Issue Title : AOE Door Mounted Arm Rest Pad Wear

Airplane Model	ATA	Minor Model(s)
737MAX	2500-00	-8

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
03/24/2017	02/23/2018	02/13/2018

Estimated Completion Date	Next Update Date

Revision Description

Project Complete

Applicability

All 737MAX 8 airplanes prior to L/N 6762 with this option selected.

Description

Several operators have reported experiencing a high wear rate on the Automatic Overwing Exit (AOE) door mounted arm rest pads and are replacing the pads on a regular basis.

Background

Boeing performed several wear and chemical tests on the current foam pads. The cleaner used by most airline operators did not degrade the foam, even after 500 passes. Acetone was also tested on the foam pads and there were immediate signs of degradation. On a different sample, Purell hand sanitizer was used for 200 passes and showed signs of degradation after only 20 passes as shown in the "Illustrations" of this article.

Boeing requested operators to posted their experience regarding damaged AOE door mounted arm rest pads via Fleet Team eXchange (FTX) 737NG-FTE-25-15017.

Status

Project complete.

Parts can be obtained through Boeing Material Services.

Interim Action

Boeing recommend operators to replace the arm rest pads as required.

Final Action

Boeing created the improved arm rest pads by wrapping the foam in a plastic shell which will provide better protection to

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

cleaners used by cleaning crews and passengers.

The new parts were incorporated into production starting at L/N 6762.

Service Letter 737-52-071 provides details of the new design for operators to purchase and replace.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 4Q 2015 (complete)

Solution Selected: November 2016 (complete)

Change Committed: May 2017 (complete)

Production Incorporation: January 2018 (complete)

Service Letter Available: February 2018 (complete)

Parts Available: February 2018 (complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Economic (FTE)	FTE-25-15017		
Service Letter (SL)	737-52-071		

Related Categories

- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board

Attachments:

a) Pad Wear 2

b) Pad Wear

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991