# FLEET TEAM DIGEST

## 737MAX-FTD-25-18003

**Issue Title :** Light Valance Shield Assembly

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 2524-31 | -8, -9 |
| **Other Model(s)** | **ECCN** | |
| 737NG | 9E991 | |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 10/04/2018 | 07/02/2024 | 05/24/2024 |
| **Estimated Completion Date** | **Next Update Date** | |

## Revision Description

Updated Milestones and Status section to reflect service letter release.

## Applicability

737 MAX airplanes with BSI (Boeing Sky Interior).

## Description

Multiple 737NG and 737 MAX operators have reported chronic in-service damage to the Light Valance Shield Assembly.

## Background

Operators are experiencing laminate damages on the panels above the overhead bins during loading and unloading of passenger luggage. The bins may not open wide enough to allow stowing bags vertically resulting in damages to adjacent panels. The damages to the light shield decorative surface include torn/peeled off laminate, scratches and scuff marks. The Cove bullnose and Center Overhead Stowage seal common to strongback panels have been found coming loose and tearing off due to luggage abuse.

Boeing is in the process of a design improvement to address the two main issues seen in service with the light shield decorative surface, as well as the cove bullnose and center overhead stowage seal common to strongback panels. The production design improvement has two parts. It will consist of a new injection molded light shield with embedded texture and color, and a new profile of the bullnose seal that is more durable by design and eliminates the need for a seal retainer. Additional details for the production improvement design change are as follows:

Change 1: A new injection molded light shield with embedded texture and color. This new design will be made from polycarbonate material, where the color will be integral to the plastic material and the texture will be applied during the molding process.

Change 2: A new profile of the bullnose seal that is more durable by design and eliminates the need for a seal retainer.

Boeing released decorative patch part 412A1811-4B to provide a temporary repair option for customers in MAR-2018.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

## Status

Boeing has incorporated a spares interchangeability note for one-way forward interchangeability between the crush core light valence shields and the new design improved injection molded light valence shields.

Boeing has released Service Letter 737-SL-25-176 with further details, including part numbers, on the new injection molded light valence shields.

## Interim Action

Boeing released decorative patch part 412A1811-4B to provide a temporary repair option for customers (MAR-2018), this is 18 inch X 12 inch sheet that includes multiple shapes to cover various damages from .75 inch to 2 inch wide.

The repair patch P/N 412A1811-4B is made of Tedlar Laminate (BAC5596 Type 14) with a pressure sensitive adhesive (PSA) backing BMS 5-91, having the same texture and color as the decorative laminate of the light valence. The repair patch can be peeled and applied to the laminate damages. This BAC5596 Type 14 is listed in 737 Aircraft Maintenance Manual (AMM) 25-00-00/801 for pressure sensitive application.

The patch removal/application procedures can be accomplished per 737 AMM Task 25-00-00-300-802:
a. Remove the damaged Decorative Tedlar piece(s) as required per Task 25-00-00-900-801 (Decorative Tedlar Removal/ Installation).
b. Peel and bond repair patch P/N 412A1811-4B to size applicable to match the prepared bond surface (overlapped bond is acceptable) per Decorative Surfaces Repair under Task 25-00-00-300-802, Apply Decorative Tedlar Laminate with a Pressure Sensitive Adhesive (adhesive-back).

Since the removal/application procedures for the patch are found in Task 25-00-00-300-802 and addressed for a customer specific issue (not a common maintenance practice for the fleet), they will not be added to the 737 AMM.

## Final Action

Boeing has incorporated a spares interchangeability note for one-way foward interchangeability between the crush core light valence shields and the new design improved injection molded light valence shields to mitigate damages on the panels above the overhead bins during loading and unloading of passenger luggage.

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Interim Solution: MAR-2018 (complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

Solution Selected: DEC-2018 (complete)

Change Committed: APR-2019 (complete)

Retrofit Solution Identification: 28-AUG-2019 (complete)

Certification Plan Initiation: DEC-2019 (complete)

Abuse Load Testing: MAR-2020 (complete)

Engineering Release: MAR-2020 (complete)

Production Incorporation: DEC-2021 (complete)

Spares Interchangeability: FEB-2023 (complete)

Service Letter release: 10-MAY-2024 (complete)

## Operator Action

Temporary repair of the Light Valance Shield laminate damages by repair patch 412A1811-4B recommended.

## Part Information

DECORATIVE ADHESIVE PATCH - Part Number 412A1811-4B, created on 03/15/2018, Size 12 inch x 18 inch, manufactured from DECORATIVE LAMINATE - P/N 401U3500-53982.

BAC 70913 COLOR WHITE, TEXTURE SKY, STANDARD CONSTRUCTION TYPE - BAC 5596, TYPE XIV

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Aircraft Maintenance Manual (AMM) | 25-00-00-300-802 | | |
| Aircraft Maintenance Manual (AMM) | 25-00-00-900-801 | | |
| Service Letter (SL) | 737-SL-25-176 | | |

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

## Attachments:

a) Light_Valance_Shield_damage

b) Light Valance Shield-Short Term Solution

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991